

150000
 CASE OWNER: Ernest CC4/AXA1700 LKK: IDAC:

Surveyor: ywk DOI: ASSIGNMENT 3/5/17 Date/Time: 28/04/2017
 Registered in Merimen: 28/04/2017

Pre-assign / CCU / FTE

Insured Vehicle No.: SGA 7842C Claim No.: C0431633
 Name of Insured: YIM ANN TONG Policy No.: G9040353
 Insured Tel No.: HP: 97538119 Make / Model: C-OPERA -1-6
 Excess Sec II :SS D.O.A: 28/4/2017 Place of Accident: JUNCTION OF BINTAI PARK & DUNJAN RD
 Is driver the owner? (YES / NO) (YES) Nature of Accident: _____
 If NO, Driver Name / Age: _____ OI GIA REPORT: YES / NO YES / TP GIA REPORT: YES / NO YES
 Driver Tel No.: _____ (V/L: YES / NO) Insured Liability: % Final ? Yes / No

SK28790H → → → →
 INSR: WSP: Supreme INSR: WSP: INSR: WSP: INSR: WSP:
 Tel: Tel: Tel: Tel: Tel: Tel:
 Liability: Liability: Liability: Liability: Liability: Liability:
 RMKS: RMKS: RMKS: RMKS: RMKS: RMKS:

Date/Time	STAGE	DATE / PIC
<u>6/1/18</u>	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
<u>14/12/18</u>	Call OI:	
<u>15/3/18</u>	After call ltr to OI: <u>TRAVAN</u>	
<u>16/3/18</u>	Documentation Check List: Handler Typist	
	Notification ltr (if non-pickup)	<input type="checkbox"/>
	After call ltr to OI:	<input type="checkbox"/>
	Authorisation To Act:	<input type="checkbox"/>
	Release Voucher:	<input type="checkbox"/>
	Final Repair Bill:	<input type="checkbox"/>
	Car Rental Invoice:	<input type="checkbox"/>
	Towing Invoice:	<input type="checkbox"/>
	LTA / GIA:	<input type="checkbox"/>
	Medical Bill:	<input type="checkbox"/>
	PIR:	<input type="checkbox"/>
	Mandate/Reject Instruction:	<input type="checkbox"/>
	LOD:	<input type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/>
	Others:	<input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: _____ Sent By: _____

FINALIZATION Date/Time: _____ Confirm with: _____ Confirm by: _____
 Repair Cost: 45 S\$ 2700.00 (14 days) Reduction: 81896.77 % 417 Email Call

FINAL SETTLEMENT Date/Time: 02/11/2021 Confirm with: KEONG Email Call
 Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 10
 Repair Cost: S\$ 2,700.00
 Loss of Rental (LOR): S\$ 514.20 (6 days) x \$85.70
 Loss of Use (LOU): S\$ (5 x days)
 Loss of Income (LOI): S\$ (5 x days)
 LOR only LOU only LOR + LOU LOR + LOI [Tick only one]
 GIA/LTA Search: S\$ _____
 Medical: S\$ _____
 Disbursement: S\$ _____ (e.g. Tow/ Independent)
 Legal Cost: S\$ _____
 Total: S\$ 3,214.20 Global Sum S\$: 3,200.00
 1) Claim status: Normal/Reject/Private Settle
 2) Report Format: TP
 3) Survey fee: \$100.00

FINAL PAYMENT Date/Time: _____ Confirm with: _____ Email Call

Payee 1: S\$ 3,200.00 Name 1: SUPREME AUTO SERVICE PTE LTD
 Payee 2: (Strike if N.A.) S\$ _____ Name 2: _____
 Payee 3: (Strike if N.A.) S\$ _____ Name 3: _____


COPY SENT 16/3/2020

ASSIGNMENT

From _____ Date _____
 Estimated Cost _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No. _____
 at Workshop No. _____
 of _____
 Insured _____
 Policy No. _____
 Claims No. _____
 Sum Insured _____ Excess _____
 Client's Record _____
 Make of Veh. _____

Veh No. SKZ 3990 H. yr Regn. 11/4/2008
 Type: M/Gar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Toyota Altis cc: 1598
 Colour: Silver A.C. Insured / Std / Nil / NA
 Sp Reading: 184930 T Recd: Insured / Std / Nil / NA
 Eng No. _____
 C No: MK053212 106101616
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: InOrder / Jammed / Leaked / Burnt or _____
 Brake: InOrder / Jammed / Leaked / Burnt or _____
 Mod: Nil / SRim / STD A/Rim or _____
 Tyre Size: F: 205/55R16 Riviera
 R: 11 Radar

Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.



Sal. or Market Value _____
 DAC Accident Report _____ Consistent? Yes or No
 GA / FR Seen _____ Consistent? Yes or No
 Est. Repairs: 4.8 days Res. Yes or No
 Lum Sum: 30 % 3 Val: Yes or No

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front _____ Rear _____
 R.Bal. 6 mm R.Bal. 4 mm
 L.Bal. 6 mm L.Bal. 4 mm
 D.O.A. 25/4/2017 D.O.I. 7/5/2017
 Survey held at Supreme Auto.

CA / REV / REP. / 24 HRS
 Date _____ Person Contacted _____ Vehicle: IN / OUT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
N/S Rear
 The U/C / Chassis frame / Body Structure affected due to collision.

Date	Time	Action	Instruction

L/S #2700/- (Rtd = 41896.23 / 417.)

Date Time File Ref: : Prel. Report
 : Final Report

Days Of Repair: _____
 Resurvey No. of Trip: _____

Survey Fee
Transaction
S + RE
Photo
Draw
TOTAL

Add Fee: Site Insp \$ _____
 Interview \$ _____
 Tech Insp \$ _____
 Weekend \$ _____

Report Format : _____
 Lump Sum / I.B.I. \$ _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/AXA17008465/Sya3	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 28-04-2017	
		Code : AXA2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SGA 7842C	Veh. Inspected	SKZ 8790H
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	28/04/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	25/04/2017	Inspection Date	03/05/2017
Survey held at	SUPREME AUTO SERVICE PTE LTD 176 SIN MING DRIVE #02-01 SIN MING AUTOCARE SINGAPORE 575721		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

SUPREME AUTO SERVICE PTE LTD

176 SIN MING DRIVE #02-01 SINGAPORE 575721
 TEL: 64520715 FAX: 64529250

ESTIMATE

EL & ASSOCIATES
 c/o 46 Lenton Plain
 Singapore 786548

Date: 3-May-17

QUANTITY	PARTICULARS	AMOUNT (\$)
RE: TOYOTA COROLLA ALTIS / SKZ8790H		
1 pc	front door protector / CMT	208.30
1 pc	rear door / 00	1,293.80
1 pc	rear door protector / CVT	175.90
1 pc	rear door regulator gear / DT	369.70
1 pc	rear door regulator motor / MN	468.90
1 pc	rear shock absorber / MN	138.50
1 pc	rear bumper / OR	437.20
1 pc	rear bumper side retainer / OR	89.50
1 pc	side kit (left) / X R	586.50
	sub-total	3,768.30
	less 25%	942.08
	sub-total	2,826.23
	ally rim s.nett	350.00
	sub-total	3,176.23
	500	600.00
	To spray painting on affected areas.	600.00
	To transfer door accessories.	50 90.00
	To remove and install rear undercarriage parts to enable repair.	20 80.00
	To replace alloy rim & perform wheel balancing.	50.00
	total	4,596.23

LKK Auto Services
 the Repairer of the following:
 • To rectify before repair
 • To display damaged parts during survey
 • Parts must be subject to confirmation
 1pc alloy rim
 • No illegal modifications allowed
 • Scope of work must be reviewed and approved by insurance company
 Acknowledged by Supplier
 Signature:
 Date:

To remove and replace all the parts mentioned above, knocking and straighten up the necessary affected areas.

L/S - 2684.36
 = 2700
 P - 1785.45
 M - 750
 L - 1220
 3355.45

4 days



19 MARCH 2018

YIM ANN TONG ✓
APT BLK417 CHOA CHU KANG AVENUE 4 ✓
#08-380 ✓
SINGAPORE 680417 ✓

Dear Sir/Madam,

OUR REF : CC4/AXA17008465/Sma3 ✓
YOUR REF : SGA 7842C ✓
ACCIDENT INVOLVING SGA 7842C AND SKZ 8790H ALONG JUNCTION OF BINJAI ✓
PARK AND DUNEARN RD (T-JUNCTION) ON 25.04.2017 ✓

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from M/s SUPREME AUTO SERVICE PTE LTD, acting on behalf of the owner of SKZ 8790H against your motor insurance policy.

Based on the accident report and accident scenario and pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant. Unless proven otherwise.

You are aware that your No-Claim Discount (NCD – if applicable) will be withheld for the time being pending for final allocation of liability in settlement by our principal.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to bevanlim@lkkauto.com within 7 days from the date of this letter **if not provided at AXA's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL.: (065) 62563561 FAX : (065) 62564315

- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at bevanlim@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Bevan Lim
Case Handler
DID: 6749 4274
FAX: 6741 4108
Email: bevanlim@lkkauto.com

c.c. AXA Insurance Pte Ltd (AXA)
(Motor Claims Dept)

Cecilia Chong (LKK Auto)

From: Cecilia Chong (LKK Auto)
Sent: Wednesday, 9 October 2019 4:27 PM
To: 'chewkeong@supreme.sg'
Subject: YOUR REF: SKZ 8790H (OUR REF: CC4/AXA17008465/Sga3) *** ACCIDENT INVOLVING SGA 7842C & SKZ 8790H ON 25/04/2017 ***

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Your ref: SKZ 8790H
Our Ref: CC4/AXA17008465/Sga3

Dear Sir/Madam,

ACCIDENT INVOLVING SGA 7842C & SKZ 8790H ON 25/04/2017

We refer to the above matter.

Kindly check and advise if your client is still interested to pursue with his third-party claim against our principal M/s AXA Insurance Pte Ltd.

Please respond and let us know within 10 days from the date of this e-mail. Otherwise, we shall have no other option but to submit our report to our principal for closure.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Cecilia Chong | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: CeciliaChong@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

 Auto
Consultants
Pte Ltd *Save the Earth. Print only when necessary.*

...CLAIM SUBFOLDER...(Pending for Survey Report)

81 Proceed Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	28 Apr 2017		28 Apr 2017 16:40 Edit Adj Rpt	S\$2,700.00 Edit Estimates	S\$2,700.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: YIM, ANN TONG , ID: S2570846F, Tel: +6597538119, Email: MEEITING@INSMART.SG									
Main Claimant: EL & ASSOCIATES , Co. Reg. No.: 53330796A									
Vehicle Reg. No.:	SKZ8790H	Date of Loss:	25/04/2017 00:00 - :59 [108 Months and 14 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / C0431633	Policy/Cover Note No.:	GA040353 (Comprehensive)						
Vehicle Reg. No. (Insured):	SGA7842C	Policy No. (Claimant):	5078245712-01						
		Excess:	S\$0.00						
Repairer:	Supreme Auto Service Pte Ltd (HQ) 176 Sin Ming Drive #02-01, Sin Ming Autocare, 575721 Sin Ming - Tel: 64528211								
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6880 4888 ... [Handled by Kitty Teo - 6880 4602]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sebastian Yeang Wai Keen] ... [Final Rpt due 11/05/2017]								
Driver/Custodian (Insured):	YIM, ANN TONG (72 / Male), NRIC: S2570846F, Tel: +6597538119 Email: MEEITING@INSMART.SG								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> • AXA_SG (13/03/2020): Re: NOTIFICATION OF MANDATE REQUEST - C0431633/SKZ8790H • AXA_SG (08/03/2020): Re: NOTIFICATION OF MANDATE REQUEST - C0431633/SKZ8790H • AXA_SG (26/09/2018): Re: TP settlement - C0431633/GA040353 • AXA_SG (26/11/2017): Re: TP settlement - C0431633/GA040353 • AXA_SG (24/10/2017): TP settlement - C0431633/GA040353 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKZ8790H (C0431633)
 [SGA7842C]
 TP
 EL & ASSOCIATES
 Apr 25 2017 12:00AM
 [YIM, ANN TONG]
 Supreme Auto Service Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View View in Browser	
Letters/Correspondences										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AXA Insurance Pte Ltd (HQ)						Thumbnail	Print		
1	28/04/17 16:39	TP SELECT LKK							Load PDF		
Photos/Images										3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	04/05/17 17:11	General View							Load JPG		
2	04/05/17 17:11	General View							Load JPG		
3	04/05/17 17:11	General View							Load JPG		
4	04/05/17 17:11	General View							Load JPG		
5	04/05/17 17:11	General View							Load JPG		
6	04/05/17 17:11	General View							Load JPG		
7	04/05/17 17:11	General View							Load JPG		
8	04/05/17 17:11	General View							Load JPG		
9	04/05/17 17:11	General View							Load JPG		
10	04/05/17 17:11	General View							Load JPG		
11	04/05/17 17:11	General View							Load JPG		
12	04/05/17 17:11	General View							Load JPG		
13	04/05/17 17:11	General View							Load JPG		
14	04/05/17 17:11	General View							Load JPG		
15	04/05/17 17:11	General View							Load JPG		
16	04/05/17 17:11	General View							Load JPG		
17	04/05/17 17:11	General View							Load JPG		
18	04/05/17 17:11	General View							Load JPG		
19	04/05/17 17:11	General View							Load JPG		
20	04/05/17 17:11	General View							Load JPG		
21	04/05/17 17:11	General View							Load JPG		
22	04/05/17 17:11	General View							Load JPG		
23	04/05/17 17:11	General View							Load JPG		
Documentation										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AXA Insurance Pte Ltd (HQ)						Thumbnail	Print		
1	28/04/17 11:08	CO-CLAIMANT TP & GIA TP_ABS							Load PDF		
2	28/04/17 11:08	EMAIL_ABS							Load PDF		
3	28/04/17 11:08	GIA SGA7842C INSD_ABS							Load PDF		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	16/03/18 16:10	LETTER TO OI							Load PDF		

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AXA17008465/SGA3Q2
Date: 17/03/2020

REFERENCE

Handling Insurer: AXA Insurance Pte Ltd Policy No: GA040353
 Claimant Vehicle No : SKZ8790H Insured Vehicle No : SGA7842C
 Date of Loss: 25/04/2017 Nature of Claim: TP Claim No: C0431633

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKZ8790H**
 Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A) Engine No: HIDDEN
 Reg. Date: 11/04/2008 (Man. Year: 2008) Chassis No: MR053ZEE106101616
 Colour: Silver Odometer: 184930 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: RIVERA 6 mm Rear Left Side: RADAR 6 mm
 Front Right Side: RIVERA 6 mm Rear Right Side: RADAR 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,176.22	2,135.45	1,040.77	32.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,420.00	1,220.00	200.00	14.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,596.22	3,355.45	1,240.77	27.00
Approved Total (Overridden) (S\$)		2,700.00		
Nett Amount (S\$)	4,596.22	2,700.00	1,896.22	41.26
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 28/04/2017
 Date Inspected: 03/05/2017 Inspected At: Supreme Auto Service Pte Ltd (HQ)
 176 Sin Ming Drive #02-01, Sin Ming
 Autocare
 Singapore 575721

Estimated Period of Repair: 4.0 days

Adjuster: Sebastian Yeang Wai Keen

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 17 Mar 2020)
Parts: 143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKZ8790H)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR PROTECTOR (CONSISTENT)	Cut	208.30 FL	*208.30 FL
2	1		*REAR DOOR (CONSISTENT)	Dented	1,293.80 FL	*1,100.00 FL
3	1		*REAR DOOR PROTECTOR (CONSISTENT)	Cut	175.90 FL	*175.90 FL
4	1		*REAR DOOR REGULATOR GEAR (CONSISTENT)	Bent	369.70 FL	*369.70 FL
5	1		*REAR DOOR REGULATOR MOTOR (CONSISTENT)	Not Necessary	468.90 FL	*- FL
6	1		*REAR SHOCK ABSORBER (CONSISTENT)	Not Necessary	138.50 FL	*- FL
7	1		*REAR BUMPER (CONSISTENT)	Broken	437.20 FL	*437.20 FL
8	1		*REAR BUMPER SIDE RETAINER	Broken	89.50 FL	*89.50 FL
9	1		*SIDE KIT (LEFT) (CONSISTENT)	Repair	586.50 FL	*- FL
10	1		*ALLY RIM (CONSISTENT)	Cut	350.00 FS	*350.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc

Sub Total (S\$)	4,118.30	2,730.60
- List Item Discount on L Items 25.00/25.00% (S\$)	942.08	595.15
Total Parts (S\$)	3,176.22	2,135.45

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REPLACE ALL THE PARTS MENTIONED ABOVE,KNOCKING AND STRAIGHTEN UP THE NECESSARY AFFECTED AREAS	New	600.00	500.00
2	TO SPRAY PAINTING ON AFFECTED AREAS	New	600.00	600.00
3	TO TRANSFER DOOR ACCESSORIES	New	90.00	50.00
4	TO REMOVE AND INSTALL REAR UNDERCARRIAGE PARTS TO ENABLE REPAIR	New	80.00	20.00
5	TO REPLACE ALLOY RIM & PERFORM WHEEL BALANCING	New	50.00	50.00
Gross Labour Cost (S\$)			1,420.00	1,220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >