

(08/11/13) wef
ASS. REC. BY: Passau

REF: CB/CT121010475/Ring 3

3082

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMN 91616
at Workshop m/s WAH HONK MOTORS
of 38, TH Guan RD East #0157
Insured: CT1 GBD 7243A

Policy No. DMCVSNA00033142104

Claims No. SNM21D205788/C02


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: 70K

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMN 91616 Yr Regn: 2018 / SEP

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: HONDA CITY 1.5 V CVT c.c 1497

Colour: GREEN A/C: Insured / Std / NI / NA

Sp. Reading: 024126 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MR4M6670KTOOD114

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 175/65R15

R: 1.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 10/16/21 D.O.I. 18/16/21

Survey held at WAH HONK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S REAR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Repair limit - 35K

Confirmed L/S \$1750, 4 repair days.

(RED \$931.40; 35%)

Date/Time, File Pass to?

: Preli. Report

1) 29/10 TYPIST

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee: : Site Insp (\$) S + RS, SI

: Interview (\$) Photos

: Tech. Invs (\$) Others

: Weekend (\$)

Report Format: TP

Lump Sum / +B.t. (\$ 1750)

TOTAL



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. SMN9161G HONDA CITY 1.5

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR'S ADJUSTMENT
LABOUR			
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	600.00	400
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	600.00	200 400
3	To remove/refix/replace wiring system at accident damaged area and check for all electrical proper function	30.00	X
4	To perform anti-rust treatment on affected areas	30.00	✓
5	To remove and refit rear seat in order to repair	100.00	60
6	To remove and refit roots lining & upholster garnish	100.00	60
7	To remove and replace rear windscreen	150.00	120
8	Wheel alignment (copy)	80.00	60
Labour Total :		1610.00	
TOTAL (PARTS & LABOUR):		2681.40	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Rasul
Hp 900 00068
4 days
4/8
18/10/21 @ 1210
Resurvey after repair



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. SMN9161G HONDA CITY 1.5

Page No. 1

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$)	SURVEYOR'S ADJUSTMENT	
<u>PARTS (LIST ITEMS)</u>					
1	Rear fender LH <i>buc ✓</i>		1064.00		
1	Rear windscreen moulding <i>re ✓</i>		119.00		
1	Rear bumper (Repair refer to labour)		0.00		
		Part Items Total:	1183.00		
			-20%	-236.60	
				946.40	
<u>SPECIAL NETT ITEMS</u>					
1	Rear fender shield clips LH <i>re ✓</i>		25.00 ✓		
1	Rear windscreen sealant <i>re ✓</i>		50.00 ✓		
1	Rear fender sealant LH <i>re ✓</i>		50.00 ✓		
		SN Items Total:	125.00		
		Total Parts	1071.40		

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 11/10/2021 15:22 (SGT)
Date of Accident 10/10/2021 15:25 (SGT)
Exact Location of Accident Near 2 Jln Uji, Singapore 678356
Additional Location Information JALAN ASAS
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMN9161G

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner CHOO AI KIM
NRIC No SXXXX308Z
Email Address KIM24K@GMAIL.COM
Mobile Phone No (Phone) +65-91918127
Alternative Phone No +65-91918127

VEHICLE PARTICULARS

Manufacturer Honda
Model City
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private car
Transmission Auto
CC 1500

INSURANCE COMPANY

Name of Insurance Company EQ Insurance Company Ltd
Type of Coverage Comprehensive
Fleet Policy No
Policy Number DMPPHQ21-006225
Cover Note Number -

DRIVER

Name of Driver CHOO AI KIM
NRIC No SXXXX308Z

Date Of Birth 15/07/1957
 Occupation Indoor
 Date Of Driving Pass 17/11/1976
 Driving experience 44 YEARS AND 11 MONTHS
 Gender Female
 Mobile Number (Phone) +65-91918127
 Alt. Phone Number +65-91918127
 Email Address KIM24K@GMAIL.COM
 Address 1 JALAN UJI
 Address complement -
 Postcode 678355
 Is the driver the policyholder? Yes
 If No, Relationship of the Driver with the Insured -
 Does Driver Own Other Vehicles? No
 Vehicle Registration Number of Other Vehicle Owned by Driver -
 Insurance Company of Other Vehicle Owned by Driver -

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Hit and run / Vandalism / Damaged whilst parked
 Weather Conditions Clear
 Road Surface Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No
 Number of vehicles involved in the accident 2
 Was anybody injured in the Accident? No
 Was any injured conveyed to hospital by ambulance? -
 Was any other vehicle or property damaged? Yes
 Number of Passengers (Including Driver) 0
 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No

DETAILS OF POLICE ACTION

Was the accident reported to the police? Yes
 Police Station Name Bukit Panjang Neighbourhood Police Centre
 Police Station Address No.1 Segar Road #01-05 Singapore 677738
 Was notice of intended Prosecution given? No
 If yes, against whom? -

CIRCUMSTANCES OF ACCIDENT

PLEASE REFER TO THE POLICE REPORT (T/20211011/2014) & SKETCH PLAN FOR ACCIDENT DETAIL.

ATTACHMENT(S)

Are accident photos available for attachment? Yes
 Was there any video captured by Car Camera? No
 Was there any audio recorded? No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBD7243A
 Vehicle Manufacturer Toyota
 Vehicle Model Dyna
 Vehicle Variant -
 Vehicle Colour -
 Vehicle Category Commercial vehicle
 Name of Driver -
 Contact Number -

Date Of Birth	15/07/1957
Occupation	Indoor
Date Of Driving Pass	17/11/1976
Driving experience	44 YEARS AND 11 MONTHS
Gender	Female
Mobile Number	(Phone) +65-91918127
Alt. Phone Number	+65-91918127
Email Address	KIM24K@GMAIL.COM
Address	1 JALAN UJI
Address complement	-
Postcode	678355
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Hit and run / Vandalism / Damaged whilst parked
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	0
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Bukit Panjang Neighbourhood Police Centre
Police Station Address	No.1 Segar Road #01-05 Singapore 677738
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

PLEASE REFER TO THE POLICE REPORT (T/20211011/2014) & SKETCH PLAN FOR ACCIDENT DETAIL.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBD7243A
Vehicle Manufacturer	Toyota
Vehicle Model	Dyna
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	-
Contact Number	-

Address -
Address complement -
Postcode -
Insurance Company Name -
Nature Of Damage -
Details of property damaged in accident -
No. Of Passenger (Including Driver) -

SKETCH PLAN


IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:


- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

 11/10/21
 Policyholder's Signature / Date & Time
 3pm
Sketch Plan

Driver's Signature (if driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel



VEH A: SMN9161G
 VEH B: GBD7243A



**SINGAPORE
POLICE FORCE**



T/20211011/2014

Police Station Of Origin:
Bukit Panjang N.P.C
1 Segar Road #01-05 SINGAPORE 677738
Tel No: 1800-8929999

2 of 3

Report No. T/20211011/2014

CONTINUATION OF REPORT

Vehicle Owner			
Name	CHOO AI KIM	ID No.	S1253308Z
Related Vehicle	SMN9161G (Car)	Contact No.	91918127
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 10/10/2021 at about 1200hrs I had parked my car(SMN9161G) along 11 Jln Asas, thereafter at about 1700hrs I discovered that there was a dent above the rear left tire. Someone had collided with my car while it was parked.

I managed to get assistance from my neighbor as his car's in-car camera was facing my car and it had captured the incident. From the footage I managed to see that a lorry(GBD7243A)'s rear had collided with the left rear of my car while it was reversing.

I have the footage from my neighbor's in-car camera.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	308Z
Vehicle No.:	SMN9161G
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Oct 2021
Vehicle Make:	HONDA
Vehicle Model:	CITY 1.5 V CVT
Primary Colour:	Silver
Manufacturing Year:	2018
Engine No.:	L15Z16201256
Chassis No.:	MRHGM6670KT000114
Maximum Power Output:	88.0kW (118 bhp)
Open Market Value:	\$15,779.00
Original Registration Date:	11 Sep 2018
First Registration Date:	11 Sep 2018
Transfer Count:	1
Actual ARF Paid:	\$15,779.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Sep 2028
PARF Rebate Amount:	\$11,834.00
COE Expiry Date:	10 Sep 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$30,868.00
COE Rebate Amount:	\$22,540.00
Total Rebate Amount:	\$34,374.00

The information contained herein is correct as at 19 Oct 2021

OK

Honda City 1.5A V

[Overview](#)

[Financial](#)

[Accessories](#)

[Similar](#)

[Research](#)

[Photos](#)

[Map](#)

 **BENEFIT AUTO**

Our Accreditations:



Member of:



Price	\$64,800		
Depreciation ⓘ	\$9,070 /yr View models with similar depre...	Reg Date	16-Jan-2018 (6yrs 2mths 27days COE left)
Mileage	62,000 km (16.5k /yr)	Manufactured ⓘ	2017
Road Tax ⓘ	\$684 /yr	Transmission	Auto
Dereg Value ⓘ	\$38,678 as of today (change)	OMV ⓘ	\$16,323
COE ⓘ	\$42,339	ARF ⓘ	\$16,323
Engine Cap	1,497 cc	Power	88.0 kW (118 bhp)
Curb Weight ⓘ	1,078 kg	No. of Owners ⓘ	1