

ASS. REC. BY: Tan Jih

REF:

CT 1

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Ms L. HoVeh No: SM 6971R Yr Regn: 2019 OCT

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Maké: Hyundai i30 c.c. 1580Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 246834 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 11M H C 85 / C 6 L 4 / 8 8 6 3 /

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15R: 2 -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. _____ D.O.I. 11/10/24Survey held at Comfort Lodge

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Rep. Format: _____

Lump Sum / L.C. (C) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SH 6971R

Make : HYUNDAI

Model : IONIQ(G3)

Date: 11/10/2021

Insurance: CHINA TAIPING

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	FRT BUMPER COVER			<i>cut</i> \$430.90
10	FRT BUMPER CLIPS			<i>cut</i> \$22.00
1	FRT BUMPER SIDE BRACKER RH			<i>de</i> \$28.00
1	FRT BUMPER MOULDING CENTRE UPPER			<i>cut</i> \$368.50
1	HEADLAMP RH			<i>cut</i> \$1,993.65
1	DAY LIGHT RH			<i>X</i> \$642.50
1	FRT BUMPER SIDE GRILLE RH			<i>cut</i> \$93.45
	SUB TOTAL			\$3,579.00
	LESS 20%			\$715.80
	DISCOUNTED TOTAL			\$2,863.20
				nett
				\$-
				nett
	Labour Charge			
	PANEL BEATING			<i>348</i> \$350.00
	SPRAY PAINTING CHARGE			<i>250</i> \$300.00
	CHECK ALL LIGHTING			<i>30</i> \$60.00
	TOTAL LABOUR			\$710.00
	ESTIMATE TOTAL			\$3,573.20

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tamplin 57445243
 -wp' 11/10/2021 4pm
 -2 days
 p/p rising before paint
 tamplin C/Maintenance

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 11.10.2021 12:50

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4128226

JC NO 305490253

CUSTOMER

VMS COMFORT TRANSPORTATION PTE LTD
CUSTOMER NO. 7010045
ADDRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
L. (R) 65508755 (O)
(P)

COUNT CARD NO.

REGN NO.

SH 6971R

MILEAGE

MAKE

HYUNDAI

FUEL

E.....1/2.....F

MODEL

IONIQ(G3)

DATE/TIME IN
11.10.2021 09:25

YR OF MANU.

30.10.2019

TARGET DATE

CHASSIS CODE

KMHC851CVLU188631

COMPLETION DATE/TIME

Accident Date: 10.10.2021


NATURE: 3P 10.10.2021

S/NO

LABOR CODE

JOB DESCRIPTION

DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Signature

Vehicle No.

SH 6971R

YY

Exit Pass

Vehicle No.:

SH 6971R

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard