



# N-51 AUTOMOTIVE PTE LTD

**Company & GST Registration No. 200616038C**

2 Kaki Bukit Avenue 2 #01-17/#01-18 /Heavy Vehicle #01-08/Spray Painting #02-27

Kaki Bukit Autohub Singapore 417921

Tel: 68420051

Fax: 67410510

Email: sales@n51.com.sg

Our Ref:

**SKM 274 C**

Your ref:

**GBA 6198 U**

12 October 2021

**CHINA TAIPING INSURANCE (S) PTE LTD**

3 ANSON ROAD #16-00

SPRINGLEAF TOWER

SINGAPORE 079909

Attn: Motor Claims Department

Dear Sir/Madam,

**NAME OF CLAIMANT : TSAO SHENG KAI, RUSSELL**

**VEHICLE NUMBER : SKM 274 C**

**YOUR INSURED VEHICLE NUMBER : GBA 6198 U**

**ACCIDENT ON 11 Oct 2021 ALONG 10 KAKI BUKIT RD 1 (S)416175 (OUTSIDE UNIT #01-36)  
AT ABOUT 10:30 HOURS**

We refer to your email/fax dated **12 Oct 2021** informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment **LKK of Adrian Ling**  
as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

**N-51 AUTOMOTIVE PTE LTD**

Kaki Bukit Autohub

2 Kaki Bukit Avenue 2

#01-18

Singapore 417921

Contact Person:

**6842 0051 / 6744 0510 (Melody/Elynn)**

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully,



.....  
**N-51 AUTOMOTIVE PTE LTD**

**FOR SURVEYOR:**

Please initial here after completion of pre-repair inspection. Thank you!

Appointed surveyor :

(Name & Signature) :

Date & Time of Inspection: