



Service Request Details

Claim

S1M03JSQ

Reference

CS3/ASM21010492/y3 

Loss Date

7 October 2021

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Report Date

12 Oct 2021 1:37:43 PM

Request Date

12 October 2021

Due Date

19 October 2021

Services

Pre-Repair Survey

Actions

Next Step

Agree to perform service

Decline Work

Vehicle Information

Incident Vehicle Registration #
SMU8476T

Make
TPVD

Model
SUZUKI

Service Address

, , ,

Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

Claim Handler

CHAN Kian Chuan
68805444
kianchuan.chan@axa.com.sg

Additional Instructions

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

New Message