



Claim	S1M03JSQ
Reference	CS3/ASM21010492/T1qy3e2 
Loss Date	7 October 2021
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Report Date	12 Oct 2021 1:37:43 PM
Request Date	12 October 2021
Due Date	
Services	Pre-Repair Survey

Actions

Next Step

Wait for: Approve
invoice

Add Invoice

Vehicle Information

Incident

SMU8476T

Vehicle
Registration #

Make

TPVD

Model

SUZUKI

Service Address

’ ’ ’

Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

CHAN Kian Chuan
68805444
kianchuan.chan@axa.com.sg

Additional Instructions

- Messages2
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes

Document Type

Document SubType

+ Upload Documents

Already Attached

NAME		DATE UPLOADED		
NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 ASM-LKKInvoice-AC2107259.pdf.pdf	Email Sent	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	20 October 2021
 LKKPreRepairInspection.pdf.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	20 October 2021

FAQ English (SG) Elaine Kuan				SUBTYPE	AUTHOR	DATE UPLOADED
	Service Requests	...	dence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	20 October 2021
	LKKPhoto.pdf.pdf		Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	20 October 2021
	AXA Immediate Advice - SMU8476T (PRS).pdf.pdf		Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	14 October 2021
	REPLY FROM TP.msg.msg		Letters and Correspondence	Third Party	KUMAR Shailendra	12 October 2021
	PRI TP PDF.pdf.pdf		Legal	Others	KUMAR Shailendra	12 October 2021
	PRI TP EMAIL FROM SOLICITOR.msg.msg		Legal	Others	KUMAR Shailendra	12 October 2021
	TP GIA.pdf.pdf		Reports & Statement	GIA Report	KUMAR Shailendra	12 October 2021