

COMFORTDELGRO ENGINEERING PTE LTD

Date: 11.10.2021

REPAIR ESTIMATE

Time: 08:27:35

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

China Taipei
CP(P) LKK- IS

JOB NO : 305490140
REGN NO : SHA7720J
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 30.09.2020
DATE/TIME IN : 09.10.2021 10:30
ACCIDENT DATE : 09.10.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 28-01-0302-2017-A RR FENDER (PETROL ONLY) LH 1 40.00 0.00 40.00 net — snap to
SUB-TOTAL : 40.00

JOB NATURE

0000 PB PANEL BEATING-SHA7720J 400.00 350.
0001 SP SPRAYPAINT-Rear Bumper Etc 600.00 500 850
SUB-TOTAL : 1,000.00

TOTAL : 1,040.00

Lamp
MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO

Tamper 97495749
WP 11/10/21 10:40 pm
Plp Resurvey after repair
tamper clock hand over
2 days

8890
2 days
#

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Co.

Acknowledged by Repairer

Signature:

Date: