COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No.: SHC2233X

Make

: Toyota

Model

: Prius (G4A)

LIS

Date: 11/10/2021

Insurance: CHINA TAIPING

MVA: MS. LOKE YY

Qty	Parts Description /	Labour	Туре	Unit Price	Amount
	PANEL SUB ASSY RR DOOR LH				\$1,258.30
9	REAR FENDER LH				\$836.70
12	ROCKER PANEL GARNISH LH				\$673.60
		SUB TOTAL			\$2,768.60
		LESS 25%			\$692.15
		DISCOUNTED TOTAL			\$2,076.45
,	PETROL STICKER				NU \$15.00
•	RR DOOR COMFORT & APP STICKER			6	\$80.00
					\$95.00
	Labour Charge			2	C =
	PANEL BEATING ~			7	\$1,100.00
	SPRAY PAINTING CHARGE		1	6	\$750.00
	TRANSFER OF DOOR				60 \$120.00
	TUFF KOTE				\$ 0 . \$50.00
		TOTAL LABOUR			\$2,020.00
		ESTIMATE TOTAL			\$4,191.45

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tarfhi 27495749 in p' 4/10/200415pm Us hising affer we per furfhir e Ikharforn a -3 duys

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



ComfortDelGro Engineering Pte Ltd

Workshops 205 Bracidell Road Singapore 5/9701 59 Loyang Drive Singapore 508969 383 Sin Ming Drive Singapore 575717

Date/Time: 11.10.2021 10:26 Page: 1

Team: ARC Repair TP(CLSO)1	JOB CARD S	ales Order: 4128175	JC NO305490146	
ISTOMER		REGN NO.: SHC2233X	MILEAGE	
COMFORT TRANSPORTATION PTE LT: 7010045	TD .	MAKE: TOYOTA	FUEL E	
DRESS 383 SIN MING DRIVE Singapore SINGAPORE 575717		PRIUS HYBRID(G4)11. 10.2021 08:50		
L. (R) 65508755 (O)		YR OF MANU. 03.10.2017	TARGET DATE	
SCOUNT CARD NO.		CHASSIS CODE JTDKB3FU403565154	COMPLETION DATE/TIME:	


Accident Date: 10.10.2021 NATURE: 3P 10.10.2021

S/NO

LABOR CODE

JOB DESCRIPTION

DESCRIPTION



HECKED & PASSED OUT BY:	Se Se		
SERVICE ADVISOR		-	CUSTOMER'S SIGNATURE
GENTOE ADVISOR			O O O TOTAL TO O O O O O O O O O O O O O O O O O O
nowledgement Slip	,	Exit Pass	
ne: No.: cle No.: SHC2233X	YY	Vehicle No.: SHC22332	X
ne of Service Advisor	Signature/Date	Name of Service Advisor	Date
e returned to Service Reception upon colle	-	To be kept by Security Guard	