

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

AUTOMOBILE INSPECTION REPORT



NITLIC	NICOME INICIID	NETTO INCOME INCOME AND CONTRACTOR AT THE LETTER OF A DISCONDING AND CONTRACTOR AT THE DISCONDING AND CONTRA					
NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC21010511/T1ucn2							
#05-0	73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			03-11-2021			
			Code:	INC4			
1. Policy Particulars :- THIRD PARTY CLAIM							
	Insured Veh.	SLD 2509Z	Veh. Ir	spected	SHA 2511D		
	Policy No.		Covera	age (\$)	0.00		
	Claim No.	MT/1147354-002	Exces	s (\$)	0.00		
	Assign From		Assign	n Date	11/10/2021		
2.	2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA PRIUS	c.c		1798		
	Engine No.	HIDDEN	Year o	f Reg.	2017		
	Chassis No.	JTDKB3FU503564109	Coloui	ſ	BLUE		
	Odometer	371866	Steerii	ng	IN ORDER		
	Brakes	IN ORDER	Modifi	cation	SPORTS RIM		
	General	GOOD					
3. Conditions of Tyres							
		Size	Make		Balance		
	R/H Front Tyre	195/65 R15	WEST	LAKE	6 mm		
	L/H Front Tyre	195/65 R15	WEST	_AKE	6 mm		
	R/H Rear Tyre	195/65 R15	WEST		6 mm		
	L/H Rear Tyre	195/65 R15	WEST		6 mm		
4.							
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.						
	DAMAGES SEE DETAILS.						
5.	General Information						
	Accident Date	09/10/2021	Inspec	tion Date	11/10/2021		
	Survey held at	•					
		59 LOYANG DRIVE SINGAPORE 508969					
5a.	5a. Remarks						
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.						
5b.	b. Estimate Days of Repair						
	ESTIMATED NORI	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days					