

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

AUTOMOBILE INSPECTION REPORT



NTU	C INCOME INSUR	ANCE CO-OPERATIVE LTD	NS/INC21010512/T	1ucn2		
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE [189556				26-10-2021		
			Code:	INC4		
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SMU 2016C	Veh. Ir	spected	SHA 6181X	
	Policy No.		Cover	age (\$)	0.00	
	Claim No.	MT/1148602-001	Exces	s (\$)	0.00	
	Assign From		Assign	n Date	11/10/2021	
2. Vehicle Particulars & Condition						
	Make & Model	HYUNDAI IONIQ	c.c		1580	
	Engine No.	HIDDEN	Year o	f Reg.	2019	
	Chassis No.	KMHC851CVKU146244	Colou	r	BLUE	
	Odometer	357420	Steerii	ng	IN ORDER	
	Brakes	IN ORDER	Modifi	cation	SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/65 R15	WEST	LAKE	6 mm	
	L/H Front Tyre	195/65 R15	WEST	LAKE	6 mm	
	R/H Rear Tyre	195/65 R15	WEST	LAKE	6 mm	
	L/H Rear Tyre	195/65 R15	WEST	LAKE	6 mm	
4.	1. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	11/10/2021	Inspec	tion Date	11/10/2021	
	Survey held at	t COMFORTDELGRO ENGINEERING PTE LTD				
		59 LOYANG DRIVE SINGAPORE 508969				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b. Estimate Days of Repair						
	ESTIMATED NORMAL PERIOD FOR REPAIR: 1 Working Days					