

(SAS-KIV)

COMFORTDELGRO ENGINEERING PTE LTD

Date: 11.10.2021

REPAIR ESTIMATE

NTUC-CP(P)

Time: 15:24:11

Page: 1

IS

LKK -

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305490273
REGN NO : SHA6181X
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 30.04.2019
DATE/TIME IN : 11.10.2021 12:00
ACCIDENT DATE : 11.10.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2537-G WING MIRROR LH

1 1,391.70 20.00 1,113.36

SUB-TOTAL : 1,113.36

JOB NATURE

0000 PB PANEL BEATING-SHA6181X

150.00

0001 SP SPRAYPAINT CHARGE

150.00 / 100

SUB-TOTAL : 300.00

TOTAL : 1,413.36

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

Tanphic 17495749
up 11/10/21 0445
01 day
Resurvey before paint
Tanphic @ 11/10/21

1113.36
150
100
1363.36 #
01 day.

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer