

HTUC - CP/P

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 11.10.2021
Time: 15:43:07
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305490274
REGN NO : SHA7971B
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 28.09.2021
DATE/TIME IN : 11.10.2021 11:15
ACCIDENT DATE : 11.10.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0104-2282-G	COVER-RR BUMPER#	1	459.40	20.00	367.52	dep de	
0002	04-01-0104-2533-G	MOULDING ASSY-RR BUMPER C	1	451.25	20.00	361.00	dep	
0003	04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60	well	
0004	04-01-0104-2288-G	BEAM-RR BUMPER	1	394.80	20.00	315.84	Rm	
0005	04-01-0104-2545-G	MOULDING-REAR BUMPER LWR	1	155.00	20.00	124.00	for car 2/870.12	
0006	28-01-0104-2029-A	VEHICLE NUMBER PLATE REAR	1 N	50.00	10.00	45.00	car	
0007	04-01-0104-1150-A	PROTECTOR MAT	1 N	50.00	1.00	50.00	well 10% 45	
							SUB-TOTAL	1,280.96 965.12

JOB NATURE

0000	PB	PANEL BEATING	400.00	350
0001	SP	SPRAYPAINT CHARGE	300.00	250
0002	L	REMOVE/REFIX REVERSE SENSOR	80.00	30
			SUB-TOTAL	780.00

Tanpin 92495749
w/p 4/20/21 @ 430
P/P Resury new parts
2 days
Tanpin @ Chuanbun

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Co.

Acknowledged by Repairer