

Our Job Ref No : 305490274

Date : 13/10/2021

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : TAUFIKH

: SHA7971B

DOA: 11/10/21

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- SGV2168M
2. The finalized amount shall be:


(a) Spare Parts after List discount	<u>\$965.12</u>
(b) Labour Charges	<u>\$630.00</u>
Total for Part-By-Part Repair Cost	<u>\$1,595.12</u>
	+
(c.) Lumpsum Repair (if applicable)	
Total for Lumpsum repair cost after Less: <u>20%</u>	<u> </u>
Final Lumpsum Repair cost	<u> </u>

3. Estimated normal period for repairs: 2 working days

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : JUMANI

Tel : 6214 8315

Fax : 65468156

Signature : taufikh

Name : TAUFIKH

Date : 28/10/21

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	-	N		
3. Survey Fees	-	-		
4. LTA Search Fee	7.49 / 2.00	YES		
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305490274
 REGN NO : SHA7971B
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G3)
 DATE OF REGN : 28.09.2021
 DATE/TIME IN : 11.10.2021 11:15
 ACCIDENT DATE : 11.10.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0104-2282-G	COVER-RR BUMPER#	1	459.40	20.00	367.52
0002	04-01-0104-2533-G	MOULDING ASSY-RR BUMPER C	1	451.25	20.00	361.00
0003	04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60
0004	04-01-0104-2545-G	MOULDING-REAR BUMPER LWR	1	155.00	20.00	124.00
0005	28-01-0104-2029-A	VEHICLE NUMBER PLATE REAR	1 N	50.00	10.00	45.00
0006	04-01-0104-1150-A	PROTECTOR MAT	1 N	50.00	1.00-	50.00

SUB-TOTAL : 965.12

JOB NATURE

0000	PB	PANEL BEATING (SHA7971B)				350.00
0001	SP	SPRAYPAINT CHARGE				250.00
0002	L	REMOVE/REFIX REVERSE SENSOR				30.00

SUB-TOTAL : 630.00

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305490274
REGN NO : SHA7971B
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 28.09.2021
DATE/TIME IN : 11.10.2021 11:1
ACCIDENT DATE : 11.10.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 1,595.12

MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO