

ASS. REC. BY: Tan Jia

REF:

INC

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S
☒	☒

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: Lim JS

Vehicle: IN / OUT

Veh No: SHB 3269S Yr Regn: 2011 May

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Maké: Toyota Prius C.C. 1798Colour: Yellow A/C: Insured / Std / NI / NASp. Reading: 362461 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: STDN13FY 40308237

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65 R15R: 2

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Wentlake

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. _____ D.O.I. 11/10/24Survey held at Comfort Lodge

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

1) _____

☐ : Final Report

Date/Time, File Return to?

2) _____

Rep. Format: _____

Lump Sum / L.B.A. ()

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

COMFORTDELGRO ENGINEERING PTE LTD

(SAS-KIV)

REPAIR ESTIMATE

LKK-

DATE: 11-Oct-21INSURANCE: NTUC

C45

MODEL: Toyota PriusMVA: LIM T SVEHICLE NO.: SHB3269S - CityCab

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Rear Trunk Outer Garnish	1		\$889.70
	Rear Trunk Lid Logo (Prius)	1		\$60.80
	Rear Trunk Lid Logo (Hybrid)	1		\$52.40
	Rear Trunk Lid Logo (Toyota Star)	1		\$52.90
	Rear Bumper	1		\$458.60
	Rear Bumper Re-Inforcement	1		\$318.80
	Rear Bumper Lower Cover-Black	1		\$552.60
	Rear Bumper Side Retainer LH	1		\$112.70
	Rear Bumper Clips	10	\$2.20	\$22.00
	Rear Bumper Lower Extension LH	1		\$232.00
	Taillamp Upper LH	1		\$557.90
	Taillamp Lower LH	1		\$548.40
	SUB TOTAL			\$3,858.80
	LESS 25%			\$964.70
	DISCOUNTED TOTAL			\$2,894.10
	Reverse Sensor	1		\$135.70
	Rear Trunk ComfortDelGro	1		\$30.00
	Rear Trunk 65521111	1		\$30.00
	Rear Trunk APPS	1		\$40.00
	SUB NETT TOTAL			\$235.70
	LESS 10%			\$23.57
	NETT TOTAL			\$212.13
	TOTAL SPARE PARTS			\$3,106.23
	Labour Charge			
	Panel Beating			\$800.00
	Spray Painting Charge			\$600.00
	Wiring Charge			\$40.00
	Tuff Kote			\$40.00
	Remove/Refix Reverse Sensor			\$120.00
	TOTAL LABOUR			\$1,600.00
	ESTIMATE TOTAL			\$4,706.23

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanpin 97495747
 WP' u/20/210445
 C/S Ngmy after report
 Tanpin like ask on
 2-3 days.

Date/Time: 11.10.2021 13:34

Page : 1

m: ARC Repair TP(CFSO)1

JOB CARD Sales Order: 4128235

JC NO305490255

MER

CITYCAB PTE LTD

7010070

MER NO.

383 SIN MING DRIVE

Singapore SINGAPORE 575717

65551188

(O)

NT CARD NO.

REGN NO.

SHB3269S

MILEAGE

MAKE

TOYOTA

FUEL

E.....1/2.....F

MODEL

PRIUS HYBRID(G4)11.10.2021 09:30

DATE/TIME IN

YR OF MANU.

02.05.2019

TARGET DATE

CHASSIS CODE

JTDKB3FU403080237


COMPLETION DATE/TIME:

ident Date: 11.10.2021
URE: 3P 11.10.2021

JOB DESCRIPTION

O LABOR CODE
010 PB

DESCRIPTION
PANEL BEATING-SHB3269S



I & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

ement Slip

Exit Pass

SHB3269S

LIMITS

Vehicle No.:

SHB3269S

ice Advisor

Signature/Date

Name of Service Advisor

Date

d to Service Reception upon collection

To be kept by Security Guard