

|   |   |   |        |   |   |   |   |      |   |   |   |   |             |
|---|---|---|--------|---|---|---|---|------|---|---|---|---|-------------|
| ◀ | < | 1 | of 2 ? | > | ▶ | ↺ | ↻ | 100% | ▼ | 📄 | ✓ | 🖨 | Find   Next |
|---|---|---|--------|---|---|---|---|------|---|---|---|---|-------------|



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                                                                  |      |                 |                     |
|----------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|------|-----------------|---------------------|
| STRIDES AUTOMOTIVE SERVICES PTE LTD                                                                                                    |                                                                                                                  |      | Ref:            | CS/SMR21010566/Uuf3 |
| 60 WOODLANDS INDUSTRIAL PARK                                                                                                           |                                                                                                                  |      | Date:           | 14/10/2021          |
| E4SINGAPORE 757705                                                                                                                     |                                                                                                                  |      | Code:           | SMR                 |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                                                                  |      |                 |                     |
| Insured Veh.                                                                                                                           | SHB 5576S                                                                                                        |      | Veh. Inspected  | GBB 6964U           |
| Policy No.                                                                                                                             |                                                                                                                  |      | Coverage (\$)   | 0.00                |
| Claim No.                                                                                                                              | TAX/10/21/2016                                                                                                   |      | Excess (\$)     | 0.00                |
| Assign From                                                                                                                            | HUA YEN                                                                                                          |      | Assign Date     | 14/10/2021          |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                                                                  |      |                 |                     |
| Make & Model                                                                                                                           |                                                                                                                  |      | c.c             | 0                   |
| Engine No.                                                                                                                             | HIDDEN                                                                                                           |      | Year of Reg.    |                     |
| Chassis No.                                                                                                                            |                                                                                                                  |      | Colour          |                     |
| Odometer                                                                                                                               | -                                                                                                                |      | Steering        |                     |
| Brakes                                                                                                                                 |                                                                                                                  |      | Modification    |                     |
| General                                                                                                                                |                                                                                                                  |      |                 |                     |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                                                                  |      |                 |                     |
|                                                                                                                                        | Size                                                                                                             | Make | Balance         |                     |
| R/H Front Tyre                                                                                                                         |                                                                                                                  |      | mm              |                     |
| L/H Front Tyre                                                                                                                         |                                                                                                                  |      | mm              |                     |
| R/H Rear Tyre                                                                                                                          |                                                                                                                  |      | mm              |                     |
| L/H Rear Tyre                                                                                                                          |                                                                                                                  |      | mm              |                     |
| <b>4. Description of Damages</b>                                                                                                       |                                                                                                                  |      |                 |                     |
|                                                                                                                                        |                                                                                                                  |      |                 |                     |
| <b>5. General Information</b>                                                                                                          |                                                                                                                  |      |                 |                     |
| Accident Date                                                                                                                          | 08/10/2021                                                                                                       |      | Inspection Date | 13/10/2021          |
| Survey held at                                                                                                                         | LIU'S BROTHER AUTO ENGINEERING WORKSHOP<br>1 KAKI BUKIT AVENUE 6 #01-01 AUTOBAY @ KAKI BUKIT<br>SINGAPORE 417883 |      |                 |                     |
| <b>5a. Remarks</b>                                                                                                                     |                                                                                                                  |      |                 |                     |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                                                  |      |                 |                     |