

SAC REC BY: Thuan

CS/AIG21010572/Vuf3

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: **FBS 7345K**

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: **SMT 2773E**Policy No: **2070059807**Claims No: **3980241366SG**

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: **13k**

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: **4** days Res.: Yes or NoLum Sum: \_\_\_\_\_ % **✓** 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: **FBS7345K**Yr Regn: **26/7,21**

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **Yamaha NMAX**c.c. **155**Colour: **Silver**

A/C: Insured / Std / NI / NA

Sp. Reading: **Not avail.**

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: **MH350588680M507A379**

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: **110/70R17**R: **110/70R17**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. **7** mmR/Bal. **7** mmL/Bal. **7** mmL/Bal. **7** mmD.O.A. **10/10/21**D.O.I. **14/10/21 1100**Survey held at **M1 Motoring**Des. of Damages: **(Ft)** Rear / O/S / N/S / UIC / Roof/Top or

The UIC / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction   |
|-------------|------------------------|
|             | <b>13500 brand new</b> |
|             | <b>BI</b>              |
|             | <b>GIA in views</b>    |
|             | <b>rebate: 7312</b>    |
|             | <b>MV: 13K</b>         |
|             | <b>NV: 5688</b>        |

28/10/2021 Submit DAR, 4 days

Date/Time File Pass to?

☐

; Prel. Report

1) 28/10 TYPIST

☐

; Final Report

Date/Time File Return to?

2

Request Formed:

MER-DAR

Lump Sum / P/B/E:

Days Of Repair: **4**

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:

☐

; Site Insp (\$

☐

; Interview (\$

☐

; Tech. Insp (\$

☐

; Wash and

Survey Fee:

Transportation:

S + RS. \$

Finitus

Others

Total



(01) Bent (2) Dented (3) Distorted (4) Cracked (5) Cut (6) Scratched  
(07) Deformed (08) Shifted (09) Buckled (10) Broken (11) Necessary  
(12) Missing (13) Torn (14) Unconfirmed (15) Not Working

## FOR MOTORCYCLE

1. Replace (✓) 2. Repair (X) 3. Check (?)  
4. Not Consistent (NC)

Vehicle No: FBS7345K

### Motorcycle

| NAC  | INC    | Item                            | CON | AC   | Qty |
|------|--------|---------------------------------|-----|------|-----|
| 1001 | 991886 | Front Number Plate              |     |      |     |
| 3001 | 995065 | Front Tyre                      |     |      |     |
| 3002 | 995095 | Front Rim                       |     |      |     |
| 3003 | 994872 | Front Tyre Rim Spoke            |     |      |     |
| 3004 | 991771 | Front Fender Wheel Guard        | 227 | ✓    |     |
| 3005 | 991283 | Front Brake Disc                |     |      |     |
| 3006 | 991281 | Front Brake Caliper             |     |      |     |
| 3007 | 991785 | Front Fork Assy                 | BT  | ✓    |     |
| 3008 | 991787 | Front Fork Inner Tube           |     |      |     |
| 3009 | 991789 | Front Fork Outer Tube           |     |      |     |
| 3010 | 991167 | Front Fork Bracket              |     |      |     |
| 3011 | 991182 | Front Fork Oil Seal             |     |      |     |
| 3012 | 991174 | Front Fork Garnish              |     |      |     |
| 3013 | 992376 | Front Headlamp Rim              |     |      |     |
| 3014 | 992328 | Front Headlamp                  |     |      |     |
| 3015 | 992337 | Front Headlamp Bracket          |     |      |     |
| 3016 | 992345 | Front Headlamp Fairing          | CRA | ✓    |     |
| 3017 | 992130 | Front Windshield                | DIS | ✓    |     |
| 3018 | 992134 | Front Wing Mirror               |     |      |     |
| 3019 | 995245 | Front LH Signal Lamp            |     |      |     |
| 3020 | 995246 | Front RH Signal Lamp            |     |      |     |
| 3021 | 992556 | Meter Casing                    |     |      |     |
| 3022 | 992553 | Meter Assy                      |     |      |     |
| 1118 | 991019 | ERP Bracket                     |     |      |     |
| 1119 | 991020 | ERP Unit                        |     |      |     |
| 3023 | 992446 | Ignition Switch                 |     |      |     |
| 3024 | 992442 | Ignition Key Assy               |     |      |     |
| 3025 | 990706 | Cowling Stay                    |     |      |     |
| 3026 | 994470 | Steering Stem                   |     |      |     |
| 3027 | 994427 | Steering Cone                   |     |      |     |
| 3028 | 992299 | Handle Bar                      |     |      |     |
| 3029 | 992312 | Handle Bar Switch               |     |      |     |
| 3030 | 992310 | Handle Bar Grip                 | 994 | 1111 |     |
| 3031 | 995184 | Handle Bar Balancer LH          |     |      |     |
| 3032 | 992300 | Handle Bar Balancer RH          | ✓   | 547  |     |
| 1122 | 992179 | Fuel Tank                       |     |      |     |
| 3033 | 990438 | Brake Reservoir                 |     |      |     |
| 3034 | 990621 | Clutch Lever                    | ✓   | 547  |     |
| 3035 | 992293 | Hand Brake Lever                |     |      |     |
| 3036 | 991119 | Side Fairing                    | DIS | 994  | ✓   |
| 3037 | 994220 | Side Fairing Top Garnish        | 547 | ✓    |     |
| 3038 | 994219 | Side Fairing Inner Garnish      |     |      |     |
| 3039 | 991118 | Fairing Shield                  |     |      |     |
| 3040 | 992047 | Front Top Fairing Inner Garnish |     |      |     |
| 3041 | 991123 | Fairing Top Garnish             |     |      |     |
| 3042 | 990538 | Center Fairing                  |     |      |     |
| 3043 | 993378 | Rear Fairing                    |     |      |     |
| 3044 | 991121 | Fairing Stopper                 |     |      |     |
| 3045 | 991117 | Fairing Lower                   |     |      |     |

| NAC  | INC    | Item                        | CON | AC | Qty |
|------|--------|-----------------------------|-----|----|-----|
| 1052 | 995074 | Radiator                    |     |    |     |
| 1053 | 992738 | Radiator Cowling            |     |    |     |
| 3046 | 994146 | Seat Assy                   |     |    |     |
| 3047 | 990915 | Engine Crash Bar            |     |    |     |
| 3048 | 990928 | Engine Guard                |     |    |     |
| 1058 | 990219 | Battery                     |     |    |     |
| 1058 | 990224 | Battery Cover               |     |    |     |
| 1059 | 990223 | Battery Bracket             |     |    |     |
| 3049 | 991144 | Foot Brake                  |     |    |     |
| 3050 | 991154 | Front Foot Rest             |     |    |     |
| 3051 | 991779 | Front Foot Rest Bracket     |     |    |     |
| 3052 | 994269 | Side Stand                  |     |    |     |
| 3053 | 992549 | Main Stand                  |     |    |     |
| 3054 | 990615 | Clutch Engine Cover         |     |    |     |
| 3055 | 992478 | Kick Starter Rubber         |     |    |     |
| 3056 | 992477 | Kick Starter Lever          |     |    |     |
| 3057 | 991145 | Foot Gear Shifter           |     |    |     |
| 3058 | 993500 | Rear Foot Rest              |     |    |     |
| 3059 | 993501 | Rear Foot Rest Bracket      |     |    |     |
| 3060 | 992581 | Exhaust Muffler Heat Shield |     |    |     |
| 3061 | 991058 | Exhaust Muffler Assy        |     |    |     |
| 1103 | 993719 | Rear LH Shock Absorber      |     |    |     |
| 1103 | 993720 | Rear RH Shock Absorber      |     |    |     |
| 3062 | 995065 | Rear Tyre                   |     |    |     |
| 3063 | 991200 | Rear Rim                    |     |    |     |
| 3064 | 994872 | Rear Tyre Rim Spoke         |     |    |     |
| 3065 | 993474 | Rear Fender Wheel Guard     |     |    |     |
| 3066 | 993443 | Rear Fender Mudflap         |     |    |     |
| 3067 | 992940 | Rear Brake Disc             |     |    |     |
| 3068 | 992936 | Rear Brake Caliper          |     |    |     |
| 3069 | 995236 | Rear Spocket                |     |    |     |
| 3070 | 990585 | Chain                       |     |    |     |
| 3071 | 990580 | Chain Guard                 |     |    |     |
| 3072 | 994530 | Swing Arm                   |     |    |     |
| 1120 | 993819 | Rear Sub frame              |     |    |     |
| 3073 | 995245 | Rear LH Signal Lamp         |     |    |     |
| 3074 | 995246 | Rear RH Signal Lamp         |     |    |     |
| 3075 | 995251 | Rear Taillamp               |     |    |     |
| 1117 | 993626 | Rear Number Plate           |     |    |     |
| 3076 | 994192 | Side Box                    |     |    |     |
| 3077 | 992927 | Rear Box                    |     |    |     |
| 3078 | 992928 | Rear Box Bracket            |     |    |     |
| 3079 | 991328 | Emblem                      |     |    |     |
| 1136 | 990247 | Sticker                     |     |    |     |

No of Items: \_\_\_\_\_

Assessor: Thavan



> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

|                                     |                   |
|-------------------------------------|-------------------|
| <b>Vehicle Owner Particulars</b>    |                   |
| Owner ID Type:                      | Singapore NRIC    |
| Owner ID:                           | 069A              |
| <b>Vehicle Details</b>              |                   |
| Vehicle No.:                        | FBS7345K          |
| Vehicle to be Exported:             | No                |
| Intended Deregistration Date:       | 27 Oct 2021       |
| Vehicle Make:                       | YAMAHA            |
| Vehicle Model:                      | NMAX 155 ABS CVT  |
| Primary Colour:                     | Silver            |
| Manufacturing Year:                 | 2021              |
| Engine No.:                         | G3L8E0556653      |
| Chassis No.:                        | MH3SG5680MJ079379 |
| Maximum Power Output:               | -                 |
| Open Market Value:                  | \$2,910.00        |
| Original Registration Date:         | 26 Jul 2021       |
| First Registration Date:            | 26 Jul 2021       |
| Transfer Count:                     | 1                 |
| Actual ARF Paid:                    | \$437.00          |
| <b>Intended PARF Rebate Details</b> |                   |
| PARF Eligibility:                   | No                |
| PARF Eligibility Expiry Date:       | -                 |
| PARF Rebate Amount:                 | \$0.00            |
| <b>Intended COE Rebate Details</b>  |                   |
| COE Expiry Date:                    | 25 Jul 2031       |
| COE Category:                       | D - Motorcycle    |
| COE Period(Years):                  | 10                |
| QP Paid:                            | \$7,506.00        |
| COE Rebate Amount:                  | \$7,312.00        |
| <b>Total Rebate Amount:</b>         | <b>\$7,312.00</b> |

The information contained herein is correct as at 27 Oct 2021

OK