

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	AXA INSURANCE	PTE LTD		Ref:	CS/ASM21010581/Avy3e2	
	8 SHENTON WAY AXA TOWERSING			Date:	13/01/2022	
	ATTN: ONG KIAN	THENG DERICK		Code:	ASM	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SJC 6159C	Veh. Inspected	d	SLC 319Z	
	Policy No.	GA577519	Coverage (\$)		0.00	
	Claim No.	S1M03JUR	Excess (\$)		0.00	
	Assign From	ONG KIAN THENG DERICK	Assign Date		14/10/2021	
2.	Vehicle Particulars & Condition					
	Make & Model	MERCEDES BENZ CLA180	c.c		1595	
	Engine No.	HIDDEN	Year of Reg.		2016	
	Chassis No.	WDD1179422N222855	Colour		RED	
	Odometer	76151 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	225/40 R18	KPATOS		6 mm	
	L/H Front Tyre	225/40 R18	KPATOS		6 mm	
	R/H Rear Tyre	225/40 R18	KPATOS		6 mm	
	L/H Rear Tyre	225/40 R18	KPATOS		6 mm	
4.	4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	12/10/2021	Inspection Dat	te	15/10/2021	
	Survey held at	YAP LEE MOTOR				
		BLK 1 KAKI BUKIT AVE 6 #01-26 AUTOBAY@KAKI BUKIT SINGAPORE 417883				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days					