

A.S.S. REC. BY:

Tanjil

REF:

CEL/14/21010605/T1093

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 9740

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: Vehicle IN / OUT
als RayVeh No: SNB30989 Yr Regn: 2018 Sep

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Seat Arona FR c.c. 999Colour: Orange A/C: Insured / Std / NI / NASp. Reading: 18553 T/Radio: Insured / Std / NI / NAEng/No: _____
C/No: VSS Z Z Z R J E J R 20490

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/50R17R: 215/50R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. _____ D.O.I. 15/10/21Survey held at Urban May

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Rep. Format: _____

Lump Sum / L&A ()

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS SI

Photos

Others

TOTAL

Woon Meng Motor Pte Ltd

Office : 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Workshop: 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Tel: 6316 1131 HP: 9730 2017 Fax: 6316 7050

42, Sungei Kadut Ave, Singapore 729666 Tel : 63268523

(Email Adress : woonmeng @singnet.com.sg)

Co Reg No. 200603678M

GST Reg No. 20-0603678M

Estimate

TP CLAIM

To : AIG Asia Pacific Insurance Pte Ltd
Motor Claims Dept

Date : 15 Oct 2021

Dear Sirs :

Fax : 6224 1047

RE : ESTIMATE COST FOR SEAT ARONA 1.0 - SNB3098Y

ACCIDENT INVOLVING SNB3098Y, SJA3742Z & OTHERS ON 14/10/2021

<u>ITEMS</u>	<u>DESCRIPTION</u>	<u>QTY</u>	<u>PRICE</u>
1	Rear bootlid <i>bt</i>	1pc	
2	Rear bootlid hinge @\$ <i>Rx</i>	1pc	
3	Rear bootlid lock <i>bt</i>	1pc	
4	Rear bootlid inner trim <i>x</i>	1pc	
5	Rear bumper <i>de</i>	1pc	
6	Rear bumper retainer @\$ <i>?</i>	1pc	
7	Rear bumper center top garnish <i>de</i>	1pc	
8	Rear bumper center lower garnish <i>de</i>	1pc	
9	Emblem <i>de</i>	1pc	
10	ARONA <i>de</i>	1pc	
11	FR <i>de</i>	1pc	
12	Rear bumper sponge <i>?</i>	1pc	
13	Rear bumper reinforcement <i>?</i>	1pc	
14	Rear end panel <i>Rx</i>	1pc	
15	Rear end panel top garnish <i>?</i>	1pc	
			\$ -
Sum Carried Forward			\$ -

Sum Carried Forward

- 16 Rear windscreen sealant
- 17 Rear number plate
- 18 Rear sensor

2pcs	\$	40.00	101 ✓
1pc	\$	35.00	
1set	\$	220.00	2004 ✓

Labour Charge & Misc

To remove, replace, repair & weld rear damaged parts. } 600.
}

To remove & replace rear windscreen glass \$120.

To R & R light wiring. 30

To anti rust 30

To R & R upholstery 80

To R & R sensor wiring 30.

To putty & spray painting 700

Total

Camera wiring - 30.

All prices quoted are subjected to 7% GST.

This is a computer generated document. No signature is required.

Taufik 97495749
W/P 15/10/21 @ 12pm
P/P Resin before paint
5 days
Taufik Khan

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	14/10/2021 18:51 (SGT)
Date of Accident	14/10/2021 13:45 (SGT)
Exact Location of Accident	PIE, Singapore
Additional Location Information	PIE towards Tuas
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SNB3098Y
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	Mohamad Ruslani Bin Samsudin
NRIC No	SXXXX995H
Email Address	inalsur11@gmail.com
Mobile Phone No	(Phone) +65-90612135
Alternative Phone No	+65-90612135

VEHICLE PARTICULARS

Manufacturer	Seat
Model	Arona
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	999

INSURANCE COMPANY

Name of Insurance Company	Etiga Insurance Pte Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	MA015586
Cover Note Number	-

DRIVER

Name of Driver	Mohamad Ruslani Bin Samsudin
NRIC No	SXXXX995H

Date Of Birth	11/06/1978
Occupation	Indoor
Date Of Driving Pass	21/03/2002
Driving experience	19 YEARS AND 7 MONTHS
Gender	Male
Mobile Number	(Phone) +65-90612135
Alt. Phone Number	+65-90612135
Email Address	inalsur11@gmail.com
Address	Blk 252 Bangkit Road, #05-402
Address complement	-
Postcode	670252
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	3
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Jurong Division Headquarters
Police Station Phone No	(Phone) +65-18007910000
Alt. Police Station Phone No	(Fax) +65-68965647
Police Station Address	No. 2 Jurong West Avenue 5 Singapore 649482
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

Refer to police report no.: J/20211014/7047.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJA3742Z
Vehicle Manufacturer	Nissan
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car

Name of Driver	Johnny
NRIC No	SXXXX403A
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	UNKNOWN
Vehicle Manufacturer	Toyota
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	Tay Wee Ting Jody
NRIC No	SXXXX647F
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	-
Gender	-
Phone No	-
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	SNB3098Y
Were seat belts worn?	-
Was this injured conveyed to hospital by ambulance?	-

[illegible]

I/We declare the foregoing particulars are true in every respect.

Driver's Signature (If driver is not the policyholder) / Date & Time	
--	--

Witnessed by Reporting Centre
Personnel



SINGAPORE POLICE FORCE



J/20211014/7047

1 of 3

POLICE REPORT (NP299)

Report No. J/20211014/7047

Police Station Of Origin
Jurong Division HQ
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No:1800-7910000

Date/Time Report Made 14/10/2021 16:52	Vide Report No.	Station Diary No.
Name Of Informant MOHAMAD RUSLANI BIN SAMSUDIN	Address 252 BANGKIT ROAD #05-402 SINGAPORE 670252	
ID Type / ID No. NRIC NO / S7816995H	Contact No. Home/Office: Mobile: 90612135	
Nationality SINGAPORE CITIZEN	Email Address INALSUR11@GMAIL.COM	
Occupation Other word processors and related operators	Sex Male	Age 43
Institution/School Name	Date of Birth 11/06/1978	Race Malay
Date/Time Of Incident 14/10/2021 13:30 - 14/10/2021 14:45	Location Of Incident 252 BANGKIT ROAD #05-402 SINGAPORE 670252	

Brief details.

Car accident involving 3 vehicles along PIE Tuas nearby Kallang Bahru. I was behind the white car which was braking and suddenly stopped which made me to stop. An impact from behind of my car and 2nd impact came from the 3rd car. The white car in front of me manage to drove off. All drivers came out and access the situation if there is any bad injuries. Particulars between drivers were exchange. Some random people park in front of my car and approached me. Letting me know that the traffic police and ambulance came to access the situation. Before the traffic police and ambulance came, the two random men which talked to us about the accident offer my wife to go to a clinic at Unihealth 24-Hr located at 178 Toa Payoh Central, #01-218. Due to their convenience I accepted their offer. My wife was told that her

Signature Of Officer Recording The Report:
Not applicable

Signature Of Informant:
The identity of the person making this report has been authenticated by Singpass. No signature is required.

Signature Of Interpreter:
Not applicable

Date/Time:
14/10/2021 16:52

Officer In-Charge Of Case:

Classification Of Case:



**SINGAPORE
POLICE FORCE**



J/20211014/7047

3 of 3

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. J/20211014/7047

Occupation	Self	Address	Blk 252 Bangkit Road #05-402 SINGAPORE 670252
Mobile No	98250851	Relation To Informant	Spouse
Person Name			
MOHAMAD RUSLANI BIN SAMSUDIN (Informant)			

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In-Charge Of Case:

Signature Of Informant:

The identity of the person making this
report has been authenticated by Singpass.
No signature is required.

Date/Time:
14/10/2021 16:52

Classification Of Case: