

B MOTOR REPAIRS SERVICES PTE LTD

IN MING DRIVE #08-03 SIN MING AUTOCITY SINGAPORE 575722
No. : 6458 0296 / 6454 8007 Fax No. : 6554 2640
Email : tbmotor@hotmail.sg
Iss. Reg. No. : 199001597D

WITHOUT PREJUDICE

KOH BOON CHIN
23 OLD UPPER THOMSON ROAD,
SINGAPORE 576216

Attention : Motor Claim Department

Estimate : ES003443

Date : 12/10/2021
Vehicle Num. : SLR5269Y
Make/Model : TOYOTA AXIO
Chassis/Eng# :
Accident Date : 08/10/2021
Claim No. :
Reference :
Policy No. : P10207089R02

Not Authorised

Purvey After Pain

4 days

82346.58

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

- | | | | | |
|---|--|------------------------------|--------|--|
| 1 | | LIST ITEMS : | | |
| 1 | | REAR LAMP LH | 548.40 | |
| 1 | | REAR BUMPER | 780 | |
| 1 | | REAR BUMPER SIDE RETAINER LH | | |
| 1 | | REAR BUMPER SIDE RETAINER RH | | |
| 1 | | REAR END PANEL | | |
| 1 | | REAR BUMPER REFLECTOR LH | | |
| 6 | | REAR BUMPER CLIPS | | |
| | | REVERSE SENSOR - NEW | | |

List Total S\$:
25.00% Discount S\$:

- LABOUR :
1. SPRAY PAINT ANTI RUST COATING
 2. CHECK & REPAIR WIRING
 3. REMOVE & REFIX REAR BUMPER PARKING SENSOR
 4. SPRAY PAINT ON ACCIDENT AFFECTED PORTIONS
 5. REPLACE REAR LAMP, END PANEL, BUMPER, WELDING PANEL BEATING AND TEST WATER LEAKING

Labour Total S\$:

Bu	652.25	✓
Bu	860.50	✓
D.V	116.10	✓
Bu	116.10	X
Bu	958.70	X
Bu	76.27	✓
8.00	48.00	✓
shot	280.00	✓
	2000	
	3,107.92	
	776.98	
	2,330.94	

un	120.00	X
	90.00	200
	120.00	500
	900.00	500
	900.00	4000
	2,130.00	

ars : Four Thousand Four Hundred Sixty & Cents Ninety-Four Only

E. & O.E.

Total S\$: 4,460.94

MOTOR REPAIRS SERVICES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: