CCY/AI621010607/Pa3 ASSIGNMENT Frun SHC 635513 / YEROGA: 20 Ciale Veh No: Estimated Cost: Type: M. Cor I M. Cycle / Bus / Van / Lorry / Parily Primo Mover ODITP/WS/TP RES/OD RES To Inspect Vehicle No Moke: at Workshop m/s Colour ΩÌ Sp.Reading T/Radlo: Insured / Std / NI / NA Insured: Eng/No: Policy No. hNA/001444F5575384 C/No: Claims No Gen. Cond; Good / Fair / Poor / Burnt Sum Insured: Sleering: In Tor / Jammed / Leaked / Burnt or (Client's Record) Inorder / Jammed / Leaked / Burnt or Make of Vch: NII I FIRIT I STO AIRIN OF Modi: 206/60RI6 Tyre Size: (Policy Condition) 206/60RI6 Remark: The veh had commenced its N/S 0/\$ BS / DUN / EXNOVA / GY / FS / LIZA / MIC OHTSU / PIR / SUMI / repair at the time of Inspection. TOYOIYOKO or Bal. or Market Value: Front Roar IDAC Accident Rport: Consistent7: Yes or No R/Bal. R/Bal. GIA / PR Seen: Consistent?: Yes or No L/Bal, L/Bal. mm mm Est. Repairs. 500 D.O.I. Lum Sum: 3 Val.: Yos or No Survey held at Drimier CA / REV / REP. / 24 HRS Des. of Damages : Frt Rear I OIS I NIS I UIC I Rooflop or Vehicle: IN / OUT Person Contacted: The U/C / Chassis frame / Body Structure affected due to collision. Date / Time Action / Instruction rebate: 16798

Labourouly		
Once Time File Pass 107 : Proll. Report 1) : Final Report	Days Of Repair: Resurvey No. of Trip:	Survey Fee:
Data/Time File Return to?	Add Fee: Site Insp (\$	Transportation:
ुः Fepert Folings :	: Interview (\$)S + RS,SI
Livery Fina (1.B.): 12	: 'Tech, Inve (\$) Officer
		7

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511 CO. REG:200707743D GST REG:200707743D

14-Oct-21

R BILL FOR KIA OPTIMA REGN NO: SHC 6355 B

ESTIMATE R	EPAIR BILL FOR KIA OPTIMA REGN NO: SH	C 6355 B		
201111111111			\$	531.00 Xr
. ,	Front bumper		\$	44.00 MAN SUS
	Front bumper emblem		S	32.00 1. XSVC
	Front bumper n/s & o/s side retainer @ \$16,00		S	16.00 7 . XSUC
	Front bumper n/s upper bracket		\$	16.00 7. XSUC
1 pc	Front bumper n/s support bracket		S	51.00 XSV C
1 pc	Front bumper n/s protector			116.00 XWC
1 pc	Front n/s wheel cover	1		384.00 X V
, ,,,	Front n/s fender	,	,	120.00 X S V C
1 pc	Front n/s fender inner shield	-	4	310.00
		Less 10%		337.90
			\$	972.10
S/NETT			\$	48.00 /h &C
1 set	Front bumper clips		\$	30.00/nlc
1 pc	Front n/s fender sticker		\$	28.00/n/c
1 set	Front n/s fender inner shield clips		Ψ	20.00 MXC
	Sundry		\$	50.00 X50c
	•		c	60.00 3 2
	To focus and adjust front n/s & o/s head lamps		\$	00.00 30
	To check front wheel alignment		\$	80.00 XNN
	To labour charge for dismantle and renew the accide damaged parts. Including knock-out, straighten, repa reshape and adjust of the same, etc	nt ír,	\$	600.00 3 <i>6</i> 0
	To putty and spray painting on front bumper, front n/s fender,front door LH, side mirror LH	3	\$	600.00360
	To apply rustproofing on the repaired and replaced pa	anels.	\$	60.00 30
	LKK A the R • To re (ALL THE REPAIR COSTS ARE SUBJECTED TO 40	Auto Consultants hence notify epairer of the following: survey before/after spray painting start a maged part(s) during resurve	y	,528.10
anochhaub.lun	THE ABOVE ESTIMATED COST OF REPAIR DO NOTO IN ANY UNFORESEEN DAMAGES.	party survey is on a "Without Prejudic egal modification(s) is allowed	ce" basis	

97235769 ANY UNFORESEEN DAMAGES.
19/10/7/ 1500 Zday Sw F
L/S after repair photo
Cabour Only

zdayswp

 Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer

Signature: Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

ehicle Owner Particulars	Company
wner ID Type:	975H
Owner ID:	
ehicle Details	SHC6355B
rehicle No.:	No
rehicle to be Exported:	28 Oct 2021
ntended Deregistration Date:	KIA
ehicle Make:	OPTIMA 1.7(A) DIESEL
Pehicle Model:	Silver
Primary Colour:	2014
Manufacturing Year:	D4FDEH313275
ingine No.:	KNAGM414MF5575384
hassis No.:	100.0 kW (134 bhp)
Maximum Power Output:	\$20,693.00
Open Market Value:	20 Jan 2015
Original Registration Date:	20 Jan 2015
First Registration Date:	0
ransfer Count:	\$13,471.00
Actual ARF Paid:	
ntended PARF Rebate Details	Yes
PARF Eligibility:	19 Jan 2023
PARF Eligibility Expiry Date:	\$8,756.00
PARF Rebate Amount:	
ntended COE Rebate Details	19 Jan 2023
COE Expiry Date:	A - Car up to 1600cc & 97kW (130bhp)
COE Category:	8
COE Period(Years):	\$52,486.00
PQP Paid:	\$8,042.00
COE Rebate Amount: Fotal Rebate Amount:	\$16,798.00
	further renewed. The vehicle must be de-registered upon COE expiry or when the very seriler.

vehicle reaches its statutory lifespan (if applicable), whichever is earlier.
The information contained herein is correct as at 28 Oct 2021

SP0I21AE0001-01 / PREMIER AUTOMOTIVE SERVICES PTE LTD ENTRY DATE & TIME: 14/10/2021 10:42 (SGT) SUBMITTED BY: ARINAWATI BINTE AMAT VERSION: 2 (14/10/2021 10:44 (SGT))



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 5. Any false reporting may be referred to the Police for Investigation.
 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving nd that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 14/10/2021 10:42 (SGT)

Date of Accident 14/10/2021 08:00 (SGT)

Exact Location of Accident New Upper Changi Rd, Singapore

Additional Location Information NEW UPPER CHANGI ROAD // BEDOK NORTH ROAD

Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Employment

1700

Vehicle Registration Number SHC6355B

INSURED/POLICYHOLDER

Is company? Yes

PREMIER TAXIS PTE LTD Name Of Registered Owner

2XXXXX975H Company Reg No

Email Address CLAIMS@PREMIERTAXI.COM (Phone) +65-91550072 Mobile Phone No

(Office) +65-62148880 Alternative Phone No

VEHICLE PARTICULARS

Manufacturer Kia Model Optima Variant

Exact purpose for which vehicle was being used at time of

accident

Are you claiming under your own insurance policy for repair to

No - Claiming third party your vehicle? Taxi Vehicle Category Auto Transmission

CC

INSURANCE COMPANY

Name of Insurance Company NTUC Income Insurance Co-operative Ltd

ThirdParty Type of Coverage Fleet Policy Yes

Policy Number 5107202885-02

Cover Note Number

DRIVER

TAN CHUNG (CHEN ZHONG) @MOHAMAD RAZIZ BIN Name of Driver **ABDULLAH**

NRIC No Date Of Birth Occupation Date Of Driving Pass Driving experience Gender

Mobile Number Alt. Phone Number Email Address

Address

Address complement

Postcode

Is the driver the policyholder?

If No. Relationship of the Driver with the Insured

Does Driver Own Other Vehicles?

Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Weather Conditions Road Surface

OTHER INFORMATION

Was any foreign vehicle involved in the accident? Number of vehicles involved in the accident

Was anybody injured in the Accident?

Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged?

Number of Passengers (Including Driver)

Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?

PASSENGER 1

Name Gender

DETAILS OF POLICE ACTION

Was the accident reported to the police? Was notice of intended Prosecution given?

If yes, against whom?

CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACH

ATTACHMENT(S)

Are accident photos available for attachment? Was there any video captured by Car Camera?

Was there any audio recorded?

SXXXX502A 31/10/1972 Outdoor 22/03/1996

25 YEARS AND 7 MONTHS

Male

(Phone) +65-94525665

CLAIMS@PREMIERTAXI.COM

BLK 252 #03-486 TAMPINES ST 21

520252 No

Hirer No

Collision - Change/cross lane

Clear Dry

No 2

No

Yes

2

No

PAX IN THE REAR SEAT - MALAY

Female

No

No

DETAILS OF OTHER VEHICLE PROPERTY 1

Yes

No

Nο

Vehicle Registration Number Vehicle Manufacturer Vehicle Model

Vehicle Variant Vehicle Colour

SMZ8788S Mercedes

White



BKETCH PLAN

IMPORTANT NOTICE

- 1 Pease report correctly the details of the accident to speed up the claims process,
- 2. This Formmust be completed by the Policyholder and/or the Authorized Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance
- Any faise reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General insurance Association
- of Singapore (GIA) for prohiving and that copies of this report will for a fee be made available upon application by interested parties,
- 7. By the indgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General insurance Association of Singapore (*GIA*) may/are parmitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' law yers/law (Irms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims
- investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by mo;

& Timo

- (w) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(callectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes,



Policyholder's Signature / Date &


14 OCT 2021 Driver's Signature (# driver is not the policyholder) / Date

Witnessed by Reporting Centre Personnel

Sketch Plan

A: SHC 6355 B B: SM78788S

NEW UPPER



Vehicle Category
Name of Driver
NRIC No
Contact Number
Address
Address complement
Postcode
Insurance Company Name
Nature Of Damage
Details of property damaged in accident
No. Of Passenger (Including Driver)

SP0121AE0001

Private car
CHAN WENG LOCK
SXXXX323E
-

Describe Circumstances of the Accident.

ON 14/10/2021 @08:00HRS, I WAS DRIVING MY TAXI (SHC 6355 B) TRAVELLING ALONG NEW UPPER CHANGI ROAD AT THE TRAFFIC LIGHT JUNCTION OF BEDOK NORTH ROAD WITH A PASSENGER ONBOARD - ON LANE 1 (ARROW ON ROAD SURFACE SHOWS RIGHT TURN ONLY).


TRAFFIC LIGHT AT THE SAID JUNCTION – SHOWED GREEN LIGHT & GREEN ARROW ON MY ROUTE FAVOUR & I PROCEED AHEAD TO TURN RIGHT (INTO BEDOK NORTH ROAD – PASSENGERS DESTINATION).

IN THE MIDST OF COMPLETING THE TURN, SUDDENLY VEHICLE B (SMZ 8788 S – M/BENZ – WHITE) WHICH WAS ON LANE 2 (ARROW ON ROAD SURFACE SHOWS STRAIGHT & RIGHT TURN) – FAILED TO KEEP IN LANE, HAD ENCROACHED & COLLIDED ONTO THE LEFT FRONT OF MY TAXI.

DUE TO THE IMPACT, MY TAXI HAD DAMAGES ON THE LEFT FRONT PORTION.
VEHICLE B HAD DAMAGES ON THE RIGHT REAR PORTION.

NO INJURY INVOLVED. NO AMBULANCE AT SCENE. NO PASSENGERS ONBOARD VEHICLE B.

* VIDEO FOOTAGE CAPTURED



Describe Circumstances of the Accident 7 1

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date &



Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Reporting Cantre Personnel

Text size +

Enquire Transaction History

Transaction History Details

Log Date/Time:

20 Jan 2015 / 08:66:15

Receipt No.:

AACCK001-AX239-150120-000005

Asset Type:

Vehicle

Transaction Amount;

\$66,097.00

Asset ID:

SHC6355B

Channel:

AA Counterless - CYCLE & CARRIAGE KIA PTE LTD

Transaction Type:

Business Transaction Reference No.:

01.02 Register New Vehicle (AA) 20150120085615996159

SHC6355B

Vehicle No.: Vehicle Type:

H10 - Public Transport Taxi (Motor Car)

Vehicle Attachment 1: Air-Con (Taxi)

Vehicle Attachment 2: Vehicle Attachment 3:

Vehicle Scheme:

Taxi (Company)

First Registration Date: 20 Jan 2015

Original Registration Date:

20 Jan 2015

Vehicle Make:

KIA

Vehicle Model:

OPTIMA 1.7(A) DIESEL

Chassis No.:

KNAGM414MF5575384

Engine No .:

D4FDEH313275

Motor No.:

Trailer Chassis No.:

Propellant:

Diesel

Passenger Capacity:

4 1685

Engine Capacity: Power Rating:

Unladen Weight:

1584

Maximum Laden

2050

Weight

Primary Color:

Silver

Secondary Color:

2014

Manufacturing Year: Open Market Value:

\$20,693.00

Minimum PARF Benefit: \$8,082.00

PARF Eligibility:

No. of Transfer:

Effective Ownership Date/Time:

20 Jan 2015 08:56:15

COE No.:

2015012001001504R

COE Expiry Date:

19 Jan 2023

COE Bid Category:

Actual QP/PQP Paid

Amount:

\$52,486.00

Lifespan Expiry Date:

19 Jan 2023