

[Service Requests](#)[Messages](#)[Claims](#)

Service Request Details

Claim	S1M03K20
Reference	CS3/ASM21010630/T1ty3 
Loss Date	11 October 2021
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Report Date	15 Oct 2021 12:08:29 PM
Request Date	15 October 2021
Due Date	
Services	Pre-Repair Survey

Actions

Next Step

Wait for: Approve
invoice

Add Invoice

Vehicle Information

Incident	SMT6433K
Vehicle	
Registration #	
Make	TPVD HONDA
Model	VEZE; 1.5

Service Address

’ ’ ’

Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

Claim Handler

LOH Cynthia

cynthia.loh@axa.com.sg

Additional Instructions

Messages1InvoicesHistoryDocumentsAssessmentMetricsNotes 1

Document TypeDocument SubType

+ Upload Documents

Already Attached

NAME		DATE UPLOADED		
NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 ASM-LKKInvoice-AC2107409.pdf.pdf	Email Sent	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	27 October 2021

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 LKKPreRepairInspection.pdf.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	27 October 2021
 LKKPhoto.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	27 October 2021
 AXA Immediate Advice _ TP - SMT 6433K.pdf.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 October 2021
 REPLY FROM SOLICITOR.msg.msg	Letters and Correspondence	Others	NIKAM Santosh Pandurang	15 October 2021
 TP GIA.pdf.pdf	Reports & Statement	GIA Report	LOH Cynthia	15 October 2021
 EMAIL FROM SOLICIOTR FOR TP REG.msg.msg	Letters and Correspondence	Others	NIKAM Santosh Pandurang	15 October 2021