

REQ. BY:

Thevan

REF:

N4AC

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SH852541

Yr Regn:

2617/17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota prius

c.c. 1798

Colour:

blue

A/C: Insured / Std / Nil / NA

Sp. Reading

54/383

T/Radio: Insured / Std / Nil / NA

Eng/No:

C/No:

JTDH83Fu303560821

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 195/65R15

R: 195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Westlake

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

7/10/21

D.O.I.

8/10/21 1615

Survey held at

Comfort

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Roof/Top or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

NO GIA given

Date/Time, File Pass to?

☐

: Prelim. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Misc. end (\$

Survey Fee:

Transportation:

S + R.S. \$

Fines

Others

TOTAL

Report Form 1:

Form 1 (Rev. 1/1/10)

Hee (Lynn)

COMFORTDELGRO ENGINEERING PTE LTD

Date: 08.10.2021

Time: 11:22:10

REPAIR ESTIMATE

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305489785
REGN NO : SH 8525H ✓
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID(G4)
DATE OF REGN : 26.07.2017
DATE/TIME IN : 08.10.2021 09:30
ACCIDENT DATE : 07.10.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 03-01-0302-2020-G	WHEEL DISC+	1	1,570.55	25.00	1,177.91	Xr
0002 04-01-0302-0573-G	FENDER SUB-ASSY FRONT RH+	1	945.30	25.00	708.97	Def
0003 04-01-0302-2297-G	EMBLEM SIDE PANEL (HYBRID	1	86.50	25.00	64.87	WAC
0004 04-01-0302-2292-A	COVER FRONT BUMPER	1	499.90	25.00	374.92	Def
0005 04-01-0302-2915-A	UNIT ASSY HEADLAMP RH	1	2,637.60	25.00	1,978.20	X50C
0006 04-01-0302-2971-G	SUPPORT FRONT BUMPER SIDE	1	81.70	25.00	61.27	WAC
0007 04-01-0302-2267-G	BUMPER CLIPS	10	22.00	25.00	16.50	WAC

SUB-TOTAL : 4,382.64

JOB NATURE

0000 PB	PANEL BEATING	800.00	700
0001 SP	SPRAYPAINT CHARGE	600.00	500
0002 17-01	CHECK ALL LIGHTING	50.00	20
0003 20-00	TUFF COAT ON AFFECTED PARTS.	50.00	10

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 08.10.2021

Time: 11:22:10

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305489785
REGN NO : SH 8525H
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID
DATE OF REGN : 26.07.2017
DATE/TIME IN : 08.10.2021 09:3
ACCIDENT DATE : 07.10.2021

JOB / PARTS DESCRIPTION	QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0004 20-08 ADJUST FRONT WHEEL ALIGNMENT	90.00		60		

SUB-TOTAL : 1,590.00

TOTAL : 5,972.64

Jumani

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

Thevan@lkhauto.com
82235769
8/10/21 1615
L/S after repair photo
3 days wp

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 08.10.2021 11:15

Page : 1

am: ARC Repair TP(CLSO)1

JOB CARD Sales Order:

JC NO305489785

OMER

COMFORT TRANSPORTATION PTE LTD

7010045

OMER NO.

ESS

383 SIN MING DRIVE

Singapore SINGAPORE 575717

65508755

(O)

(R)

(P)

OUNT CARD NO.

REGN NO:

SH 8525H

MILEAGE

MAKE:

TOYOTA

FUEL

E.....1/2.....F

MODEL

PRIUS HYBRID(G4)08.10.2021 09:30

DATE/TIME IN

YR OF MANU.

26.07.2017

TARGET DATE

CHASSIS CODE

JTDKB3FU303560821

COMPLETION DATE/TIME:

JOB DESCRIPTION


Accident Date: 07.10.2021

ATURE: 3P.07.10.2021

NO

LABOR CODE

DESCRIPTION



IKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

ledgement Slip

Exit Pass

Vehicle No.:

SH 8525H

No.:

SH 8525H

JU NTUC

f Service Advisor

Signature/Date

Name of Service Advisor

Date

turned to Service Reception upon collection

To be kept by Security Guard

INSURER ENQUIRY

Find insurer

Vehicle reg. no.

SNB7141D

Date of Accident

07/10/2021



Reset

% RESULT & RECEIPT

TP Insurer Enquiry

Insurance NTUC Income Insurance Co-op...

Period of Insurance 02/10/2021 - 01/10/2022

Requested By Huang Xiao Yan (COMFORTDEL...

Requested Date 08/10/2021 10:46

Payment details

Request Amount: **S\$1.87**

GST Amount: **S\$0.13**

Total Amount Due (GST Inclusive): **S\$2**

General Insurance Association

Records Management Centre

GST Registration No: **M400017735**