



Claim	S1M03K1A
Reference	CS3/ASM21010667/R1vy3e2 
Loss Date	14 October 2021
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Report Date	15 Oct 2021 10:01:03 AM
Request Date	18 October 2021
Due Date	
Services	Pre-Repair Survey

Actions

Next Step

Wait for: Approve
invoice

Add Invoice

Vehicle Information

Incident

FBF9170C

Vehicle
Registration #

Make

TPVD

Model

Yamaha

Service Address

, , ,

Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

Additional Instructions

- Messages2
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes 1

Document Type

Document SubType

+ Upload Documents

Already Attached

NAME		DATE UPLOADED		
NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 ASM-LKKInvoice-AC2107393.pdf.pdf	Email Sent	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	27 October 2021
 LKKPreRepairInspection.pdf.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	27 October 2021

[FAQ](#)[English \(SG\) ▼](#)[Elaine Kuan ▼](#)[Service Requests](#)[FBF 9170C LKKPhotosIn4](#)

TYPE

SUBTYPE

AUTHOR

DATE
UPLOADEDForms / Claim
Documents

Others

LKK AUTO CONSULTANTS
PTE LTD (TP)19
October
2021 [FBF 9170C LKKPhotosIn4
_compressed.pdf.pdf](#)

Evidence

Photos

LKK AUTO CONSULTANTS
PTE LTD (TP)19
October
2021 [PRI TP EMAIL FROM SOLICITOR.msg.msg](#)

Legal

Others

KUMAR Shailendra

18
October
2021 [TP GIA.pdf.pdf](#)Reports &
Statement

GIA Report

KUMAR Shailendra

18
October
2021 [PRI TP PDF.pdf.pdf](#)

Other

Other

do not reply

18
October
2021 [OI CCTV SHD7258L RESIZED 2
inf1_0464_20211014_111211_l.mp4](#)

Evidence

Videos

LOH Cynthia

18
October
2021

[FAQ](#)[English \(SG\) ▼](#)[Elaine Kuan ▼](#)

TYPE

SUBTYPE

AUTHOR

DATE
UPLOADED[Service Requests](#)[INSG GIA -SHD7258L.pdf](#)

Legal

Others

KUMAR Shailendra

18
October
2021 [INSG GIA -SHD7258L.pdf.pdf](#)Reports &
StatementAccident
statement

STACEY Ng Pei Sze 2

15
October
2021