COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHC1150H

Make

: Toyota

Model : Prius

L18.

Date: 18.10.2021

Insurance: AIG

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Туре	Unit Price	Amount
	1 FRT FENDER HYBRID EMBLEM RH			\$86.50
	1FRONT FENDER SUB ASSY RH			\$945.30
	1FRONT FENDER SHIELD RH			\$198.50
	1FRT FENDER RETAINER RH		- "	\$86.30
	1FRONT BUMPER FOG LAMP			\$920.00
	1HEADLAMP RH			\$2,637.60
	1FRONT BUMPER COVER			\$499.90
	1 FRONT BUMPER SIDE BRACKET RH			\$82.30
	0 FRONT BUMPER CLIPS			\$22.00
	1 FRT WHEEL HUB CAP RH			\$177.70
	SUB TOTAL			\$5,656.10
	LESS 25%			\$1,414.03
	DISCOUNTED TOTAL			\$4,242.08
	FRT TYRE RH	Nett		\$216.00
				\$216.00
	Labour Charge			
	PANEL BEATING			\$900.00
	SPRAY PAINTING CHARGE			\$600.00
	CHECK ALL LIGHTING			\$50.00
	TUFF KOTE			\$60.00
	TOTAL LABOUR			\$1,610.00
	ESTIMATE TOTAL			\$6,068.08

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

ThewareChhauto.com
82235769
18/10/21 1630
US after repair photo
3 clays wp

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SJ0421AI000I / JP Knights Pte Ltd ENTRY DATE & TIME: 18/10/2021 19:15 (SGT) SUBMITTED BY: Caymen VERSION: 1 (18/10/2021 19:15 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Please report correctly the details of the accident to speed up the claims process.

2. This Form must be completed by the Policyholder and/or the Authorised Driver

3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

18/10/2021 19:15 (SGT) Date of Submission 17/10/2021 10:40 (SGT) Date of Accident **Exact Location of Accident** Sengkang W Way, Singapore Additional Location Information TURN TO FERNVALE ROAD Singapore Country/State of Loss

DETAILS OF OWN VEHICLE

Toyota

SHC1150H Vehicle Registration Number

INSURED/POLICYHOLDER

Is company? COMFORT TRANSPORTATION PTE LTD Name Of Registered Owner 1XXXXX821R Company Reg No fleetsafety@cdgtaxi.com.sg **Email Address** (Phone) +65-91259823 Mobile Phone No (Office) +65-65508768 Alternative Phone No

VEHICLE PARTICULARS

Manufacturer

CC

Prius Model Variant Exact purpose for which vehicle was being used at time of Private hire accident Are you claiming under your own insurance policy for repair to No - Claiming third party your vehicle? Taxi Vehicle Category Auto Transmission 1798

INSURANCE COMPANY

AXA Insurance Pte Ltd Name of Insurance Company ThirdPartyFireTheft Type of Coverage Yes Fleet Policy VFX/P2419138 Policy Number Cover Note Number

DRIVER

TAN CHONG BOON Name of Driver SXXXX375B NRIC No

Outdoor Occupation 04/12/1981 Date Of Driving Pass 39 YEARS AND 10 MONTHS Driving experience Male Gender (Phone) +65-91259823 Mobile Number Alt. Phone Number fleetsafety@cdgtaxi.com.sg **Email Address BLOCK 658A PONGGOL EAST** Address #17-705 Address complement 821658 Postcode No Is the driver the policyholder? If No, Relationship of the Driver with the Insured Hirer Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Collision - Change/cross lane Type of Accident Clear Weather Conditions Dry Road Surface OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident 2 Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Yes Was any other vehicle or property damaged? Number of Passengers (Including Driver) 3 Has the driver been approached by unknown person(s) No soliciting/offering accident claims assistance? PASSENGER 1 PASSENGER Name Female Gender PASSENGER 2 **PASSENGER** Name Female Gender DETAILS OF POLICE ACTION No Was the accident reported to the police? No Was notice of intended Prosecution given? If yes, against whom? CIRCUMSTANCES OF ACCIDENT ON 17/10/21 AT ABOUT 1040HRS I WAS DRIVING VEHICLE A SHC1150H ALONG SENGKANG WEST WAY ROAD AND WANTED TO TURN LEFT INTO FERNVALE ROAD WITH TWO PASSENGERS.I AT EXTREME LEFT LANE.AS I WAS TRAVELLING WITHIN MY LANE SUDDENLY VEHICLE B SML8430Y FILTER INTO MY LANE AND GRAZED ONTO MY VEHICLE FRONT RIGHT.EXCHANGED PARTICULAR AND NO INJURIES AT POINT OF TIME. ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? Yes FILE IS NOT SUITABLE Reasons for not uploading a video of the accident No Was there any audio recorded?

DETAILS OF OTHER VEHICLE PROPERTY T

N. A.	SML8430Y
Vehicle Registration Number	Kia
Vehicle Manufacturer	Cerato
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	Private car
Vehicle Category	ONG LONG SUN MICHAEL
Name of Driver	SXXXX164J
NRIC No	
Contact Number	7. F. C.
Address	
Address complement	
Postcode	-
Insurance Company Name	
Nature Of Damage	
Details of property damaged in accident No. Of Passenger (Including Driver)	1


SKETCH PLAN

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act(PDPA)

Lunderstand, acknowledge, agree and consent that

- (a) My insurer , my w orkshop and the General Insurance Association of Singapore (*GIA*) may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) w ho have insured vehicle(s) involved in this accident (all insurer(s) w ho have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes") (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Describe Circumstances of the Accident

ON 17/10/21 AT ABOUT 1040HRS I WAS DRIVING VEHICLE A SHC1150H ALONG SENGKANG WEST WAY ROAD AND WANTED TO TURN LEFT INTO FERNVALE ROAD WITH TWO PASSENGERS.I AT EXTREME LEFT LANE.AS I WAS TRAVELLING WITHIN MY LANE SUDDENLY VEHICLE B SML8430Y FILTER INTO MY LANE AND GRAZED ONTO MY VEHICLE FRONT RIGHT.EXCHANGED PARTICULAR AND NO INJURIES AT POINT OF TIME.

Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date &

Driver's Signature (If driver is not the policyholder) / Date & Time

/ 100 Pas

18/0/20

Witnessed by Restring Cent Personnel

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID: Vehicle Details	821R
Vehicle No.:	SHC1150H
Vehicle to be Exported:	No
Intended Deregistration Date:	27 Oct 2021
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	2ZRS060857
Chassis No.:	JTDKB3FU603563227
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$29,007.00
Original Registration Date:	10 Aug 2017
First Registration Date:	10 Aug 2017
Transfer Count:	0
Actual ARF Paid: Intended PARF Rebate Details	\$5,000.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 Aug 2025
PARF Rebate Amount: Intended COE Rebate Details	\$3,750.00
COE Expiry Date:	09 Aug 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$36,320.00
COE Rebate Amount:	\$17,183.00
Total Rebate Amount: Message	\$20,933.00
Please note that the 8-year COE for this vehicle cannot	be further renewed. The vehicle must be de-registered upon COE expiry or when the

vehicle reaches its statutory lifespan (if applicable), whichever is earlier. The information contained herein is correct as at 27 Oct 2021 $\,$

OK



ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Maintine + 00 0000 0200 1000 1000 Workshops 205 Braddell Road Singapore 579701 59 Loyang Drive Singapore 508969 383 Sin Ming Drive Singapore 575717

Date/Time: 18.10.2021 12:38

Page: 1

JOB CARD Sales Order: 4130592 ARC Repair TP(CLSO)1 am: JC NO305491105 REGN NO.: SHC1150H OMER MILEAGE COMFORT TRANSPORTATION PTE LTD MAKE FUEL 7010045 OMERNO. 7010045
SSS 383 SIN MING DRIVE TOYOTA E.....F PRIUS HYBRID(G4)18.10.2021 09:25 Singapore SINGAPORE 575717 65508755 (O) YR OF MANU. 10.08.2017 TARGET DATE (P) CHASSIS CODE JTDKB3FU603563227 COMPLETION DATE/TIME: UNT CARD NO. JOB DESCRIPTION


cident Date: 17.10.2021 FURE: 3P 17.10.2021

)MEOPTDEI CDO

VO

LABOR CODE

DESCRIPTION



ComfortDelGro Engineering Pte Ltd

D & PASSED OUT BY:		
SERVICE ADVISOR		CUSTOMER'S SIGNATURE
gement Slip	Exit Pass	
SHC1150H YY	Vehicle No.: SHC1150H	
rvice Advisor Signature/Date	Name of Service Advisor	Date
ed to Service Reception upon collection	To be kept by Security Guard	