

REF:

## ASSIGNMENT

Veh No: SMQ143C Yr Regn: 2019 / Oct.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Fit c.c. 1456

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading 142896 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: GP51335 108 \*

Gen. Cond. Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/65R15

R: 185/65 R15.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Greenlander

Front Rear

R/Bal. 26 mm R/Bal. 26 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. \_\_\_\_\_ D.O.I. 18/10/21.

Survey held at Advance

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

Front N/S

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction |
|-------------|----------------------|
|             | TP III               |
|             |                      |
|             |                      |
|             | MV :                 |
|             | PV :                 |
|             | Nett:                |
|             |                      |
|             |                      |
|             |                      |

☐: Prelim. Report☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: : Site Insp (\$

Interview 13

Tech. Invs (3)

Survey Fee:

Transportation:

Phonics

11 Others