

Claim	S1M03K0M
Reference	CS3/ASM21010734/Eqy3e2 
Loss Date	14 October 2021
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Report Date	18 Oct 2021 6:24:00 PM
Request Date	19 October 2021
Due Date	
Services	Pre-Repair Survey

Actions

Next Step

Wait for: Approve invoice

Add Invoice

Vehicle Information

Incident	FW9236K
Vehicle	
Registration #	
Make	TPVD Yamaha
Model	Rx115

Service Address

...

Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

ANG Yvonne

yvonne.ang@axa.com.sg

Additional Instructions

- Messages2
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes

Document Type

Document SubType

+ Upload Documents

Already Attached

NAME		DATE UPLOADED		
NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 ASM-LKKInvoice-AC2107334.pdf.pdf	Email Sent	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	25 October 2021
 LKKPreRepairInspection.pdf.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	25 October 2021

FAQ

English (SG) ▾

Elaine Kuan ▾

Home

Service Requests

...

lence

Photos

LKK AUTO CONSULTANTS PTE LTD (TP)

25 October 2021

			SUBTYPE	AUTHOR	DATE UPLOADED
 LKKPhoto.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	25 October 2021	
 FW9236K TP GIA.pdf.pdf	Reports & Statement	GIA Report	NIKAM Santosh Pandurang	19 October 2021	
 EMAIL FORM SOLICITOR FOR TP REG.msg.msg	Letters and Correspondence	Others	NIKAM Santosh Pandurang	19 October 2021	
 AXA Immediate Advice - FW9236K (PRS).pdf.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	19 October 2021	
 SJ0421AE0008-SHC3663G.pdf.pdf	Reports & Statement	Accident statement	STACEY Ng Pei Sze 2	14 October 2021	