

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No. 139007130R GS1 Reg. No. 13-3007130-R					
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Ref	: CS/AGI21003900/Atf3n2	
		TINSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Daf	te: 21/10/2021	
			Cod	de: AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLE 4186C	Veh. Inspected	SLR 6031J	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C10009554/ST	Excess (\$)	0.00	
	Assign From	IVY RATILLA	Assign Date	25/03/2021	
2.	2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ A200	c.c	1595	
	Engine No.	HIDDEN	Year of Reg.	2017	
	Chassis No.	WDD1760432J513350	Colour	WHITE	
	Odometer	28347 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	225/45 R17	BRIDGESTONE	6 mm	
	L/H Front Tyre	225/45 R17	BRIDGESTONE	6 mm	
	R/H Rear Tyre	225/45 R17	BRIDGESTONE	6 mm	
	L/H Rear Tyre	225/45 R17	BRIDGESTONE	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION AND UNDERCARRIAGE.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	24/03/2021	Inspection Date	26/03/2021	
	Survey held at	d at ISHARE AUTO PTE. LTD.  8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	o. Estimate Days of Repair				

12 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: