

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III21010757/EYA3Q2**Date:** 10/04/2023**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MPC0005540
Claimant Vehicle No : FBQ1738K **Insured Vehicle No :** SMF5348D
 Date of Loss: 23/09/2021 Nature of Claim: TP Claim No: MPC2021D0004156

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBQ1738K**
 Make & Model: ZONTES X310, 312cc Engine No: ZT180MNK0000496
 Reg. Date: 08/08/2019 (Man. Year: 2019) Chassis No: LD3PDP6J6K1600252
 Colour: Grey Odometer: 26499 km
 Engine Capacity: 312 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 120/60-17 Rear Tyre Size: 160/60-17
 Front Left Side: Pirelli 3 mm Rear Left Side: Pirelli 3 mm
 Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	106.20	106.20	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	330.00	110.00	220.00	66.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	436.20	216.20	220.00	50.44
+ GST 7.00/7.00% (S\$)	30.53	15.13	15.40	50.44
Nett Amount (S\$)	466.73	231.33	235.40	50.44
+ Loss of Use (1.0 x S\$30.00/day) (S\$)		30.00		
Nett Liability (S\$)		261.33		

INSPECTION

Date of Assignment: 19/10/2021
 Date Inspected: 19/10/2021 Inspected At: Choong Kok Agency Pte Ltd (Jurong)
 Block 343, Jurong East Street 31, #01-63
 Singapore 600343
 Estimated Period of Repair: 1.0 days

Adjuster: CHEN TSUE YEE**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 10 Apr 2023)	
Parts:	N/A	ZONTES X310 312cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBQ1738K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*GEAR PEDAL	Bent	118.00 FL	*118.00 FL
F=Franchise part. L=ListItemDisc.						
Sub Total (S\$)					118.00	118.00
- List Item Discount on L Items 10.00/10.00% (S\$)					11.80	11.80
Total Parts (S\$)					106.20	106.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING	New	80.00	60.00
2	LABOUR	New	250.00	50.00
Gross Labour Cost (S\$)			330.00	110.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >