



Your Ref: S1M03FPL

Date: 10<sup>th</sup> Nov 2021

Our Ref: CS3/ASM21008601/T1qy3e2-1

**M/s Axa Insurance Pte Ltd**

8 Shenton Way #24-01

Axa Tower

Singapore 068811

(The Motor Claims Department)

Attn: Chan Kian Chuan

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SNA 6767K  
INSURED VEHICLE: SHC 2020T  
ACCIDENT DATE: 15/08/2021**

We thank you for your instruction on 06/10/2021.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SNA 6767K from M/s Kelvin Automotive Appraising Services.
- b) Singapore Accident Statement of Vehicles SNA 6767K and SHC 2020T.
- c) Colour damaged vehicle photographs of SNA 6767K.

Pre-Repair Inspection Date : 17/08/2021 at M/s Apex Motoring, 25 Kaki Bukit Road 4 #01-55 Synergy @ KB, Singapore 417800.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SNA 6767K
Make & Model	: Honda Fit Basic 1.3 CVT
Year of Registration	: 2021
Chassis Number	: GR11020367
Engine Capacity	: 1317 cc

2. We recommend that the repairs of the entire damage require about 8 (Eight) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.