



Service Request Details

Claim S1M03K7Q

Reference

CC4/ASM21010792/rs3 🥒

Loss Date

17 October 2021

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Report Date

19 Oct 2021 8:49:55 AM

Request Date

20 October 2021

Due Date

27 October 2021

Services

Pending verification - Direct Settlement

Actions

Next Step

Agree to perform service



Menu

Accept Work

Vehicle Information

Incident Vehicle Registration #

FBG1097D

Make

TPVD Yamaha

Model

Fz16

Service Address

, , ,

Primary Contact/Insured

CHEONG SIEW MENG BLK 450 BT PANJANG RING ROAD, #06-591, 670450, Singapore

HONGYEN.CHONG@ALLINK.COM.SG

Claim Handler

KOH Janice

92393031

janice.kohlc@axa.com.sg

Additional Instructions

WS: SG 98 Motor

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

