

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315



**AUTOMOBILE INSPECTION REPORT** 



NTUC	C INCOME INSUR	ANCE CO-OPERATIVE LTD	NS/INC21010797/\	/ucn2		
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556				26-10-2021		
			Code:	INC4		
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SMG 6451B	Veh. Ir	nspected	SHB 3415L	
	Policy No.		Cover	age (\$)	0.00	
	Claim No.	MT/1147681-002	Exces	s (\$)	0.00	
	Assign From		Assig	n Date	13/10/2021	
2. Vehicle Particulars & Condition						
	Make & Model	HYUNDAI IONIQ	c.c		1580	
	Engine No.	HIDDEN	Year o	f Reg.	2021	
	Chassis No.	KMHC851CVLU184767	Colou	r	YELLOW	
	Odometer	68291	Steeri	ng	IN ORDER	
	Brakes	IN ORDER	Modifi	cation	SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/65 R15	WEST	LAKE	5 mm	
	L/H Front Tyre	195/65 R15	WEST	LAKE	5 mm	
	R/H Rear Tyre	195/65 R15	WEST	LAKE	5 mm	
	L/H Rear Tyre	195/65 R15	WEST	LAKE	5 mm	
4.						
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	12/10/2021	Inspec	tion Date	13/10/2021	
	Survey held at	COMFORTDELGRO ENGINEERING PTE LTD				
		59 LOYANG DRIVE SINGAPORE 508969				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b. Estimate Days of Repair						
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days					