

NTUC-CPIP)

COMFORTDELGRO ENGINEERING PTE LTD

Date: 13.10.2021

Time: 10:31:19

Jumant

REPAIR ESTIMATE

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305490436
REGN NO : SHD4140L ✓
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 14.11.2019
DATE/TIME IN : 12.10.2021 16:35
ACCIDENT DATE : 12.10.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2282-G COVER-RR BUMPER#	1	459.40	20.00	367.52	Kr
0002 04-01-0104-2533-G IONIQV2 MOULDING ASSY-RR	1	451.25	20.00	361.00	/cut
0003 04-01-0101-0111-G BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60	/nic
0004 04-01-0104-2288-G BEAM-RR BUMPER	1	394.80	20.00	315.84	? XSVU
0005 28-01-0104-2029-A VEHICLE NUMBER PLATE REAR	1 N	50.00	10.00	45.00	/crq

SUB-TOTAL : 1,106.96

JOB NATURE

0000 PB	PANEL BEATING	400.00	350
0001 SP	SPRAYPAINT CHARGE	300.00	250
0002 L	REMOVE/REFIX REVERSE SENSOR	80.00	30

SUB-TOTAL : 780.00

1886.96

Thuan@lkhauto.com
82235269
13/10/21 /600
P/P get bto paint photo
2 days up

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: