

## **SMRT Accident Vehicle Repair Estimates**

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 20/10/2021 User ID : GohKK2

STATE STATE	STATE OF	A CONTRACTOR	Sect	ion D - Detail	s of Repair Es	timates			
rt 1 - Labour	Norks	ALIES NEWSTREET	CONTRACTOR OF STREET	1 70019 (5)					
				Quotation from AR				Adjusted by Surveyor, if applicable	
ob Scope				MORE RESIDENCE TO THE PROPERTY OF THE PERSON				530	
O REPAIR RH PORTION				\$795.00				230	
otal Labour				\$795.00					
art 2 - Spray	Painting & Pa	inel Beating Relate	ed Works	1033 N. 133					
				Quotation from ARC				Adjusted by Surveyor, if applicable	
Job Scope				Quotation from ARC					
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS				\$432.00				2(2	
Total Spray Painting & Panel Beating				\$432.00					
Part 3 - Other	Costs - Accid	dent and Accident	Repair Related Expo	nse .		TO STATE OF THE PARTY.		STATE OF THE	
Job Scope				Quotation from ARC				Adjusted by Surveyor, if applicable	
Total Other Costs									
Part 4 - Span	Parts / Mate	rial Usage	STATE OF THE PARTY	SECRETAL SECOND	CONTRACTOR				
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
Total	1								
Added Spare	Parts / Mate	rial Usage After Su	rveyor Signed off	Van Van	200	THE PARTY	100000000		
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
			The same of the sa		A CONTRACTOR OF THE PARTY OF TH	Control of the Contro			
Total	THE RESERVE				and the same of the latest		AV.		

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Parul
Hp 90000068

2 days
45 P/P

20/10/21/1545

Regalter report