

HTUC-(4sum)

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 14.10.2021
Time: 14:26:37
Page: 1
Jumani

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305490585
REGN NO : SHA1780A ✓
MILEAGE : 0000000000 ✓
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 11.01.2017
DATE/TIME IN : 14.10.2021 11:30
ACCIDENT DATE : 13.10.2021

JOB / PARTS DESCRIPTION QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0103-0579-G	COVER ASSY-RR BUMPER#	1	553.00	20.00	442.40	✓/ent
0002	04-01-0103-0738-G	COVER-RR BUMPER LWR#	1	228.00	20.00	182.40	✓/scr
0003	04-01-0103-0740-G	BEAM-RR BUMPER#	1	428.40	20.00	342.72	1. X SUC
0004	04-01-0103-0739-G	ABSORBER-RR BUMPER ENERGY	1	103.50	20.00	82.80	1. X SUC
0005	04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	20.00	20.00	16.00	✓/ncc
							SUB-TOTAL : 1,066.32

JOB NATURE

0000	PB	PANEL BEATING		300.00		280	
0001	SP	SPRAYPAINT CHARGE		300.00		250	
0002	20-05	RENEW ADVERTISEMENT STICKER-Bumper		50.00		✓/ncc	
0003	L	REMOVE/REFIX REVERSE SENSOR		80.00		30	
							SUB-TOTAL : 730.00

Thuan@lkkauto.com
82235769
14/10/21 1630
2days w/p
L/S after repair photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: