

11/10/21 Thuvan

CS/ASG 21010873/Vuf3

ASSIGNMENT

From: _____ State: _____
 Estimated Cost: _____
 QD/TP/WS/TP RES/OD RES/EVA/INV/MV
 To Inspect Vehicle No: _____
 at Workshop m/s: _____
 of: _____
 Insured: YP 7584E
 Policy No: 1800110064
 Claims No: 8715571172SG
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: X 12 0.5 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SBS 8308LV ✓ Yr Regn: 18/8, 2008
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Scania KUB4X2 c.c. 8867
 Colour: Multi Colour A/C: _____ Insured / Std / Nil / NA
 Sp. Reading: 1218149.9 T/Radio: Insured / Std / Nil / NA
 Eng/No: _____
 C/No: YS 2h4X 2000 1861340
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt / or
 Brake: In order / Jammed / Leaked / Burnt / or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyro Size: F: 275/70 R22.5
 R: 275/70 R22.5
 BS OUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: _____ Rear: _____
 R/Bal. 5 mm R/Bal. 5 mm
 L/Bal. 5 mm L/Bal. 5 mm
 D.O.A. 21/10/21 D.O.I. 22/10/21 141630
 Survey held at bedoh bus depot
 Des. of Damages: Fr Rear / O/S / N/S / U/C / Roof/Top or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	GIA in views
10/11/21	Submit \$221 (un-confirmed) (Red 0)

Date/Time File Pass to? ☐ : Provl. Report
☐ : Final Report

Days Of Repair: 0.5
 Resurvey No. of Trlp: _____

Date/Time File Return to?
 10/11/21-typist

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Insp (\$)
☐ : W/S&I end (\$)

Survey Fee:	
Transportation:	
S + RS: \$	
Fuel/Bus	
Coffee	
Total	

Report Format:

Letter Sign / B.S.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

653M

Vehicle Details

Vehicle No.:

SB58308L

Vehicle to be Exported:

Yes

Intended Deregistration Date:

01 Nov 2021

Vehicle Make:

SCANIA

Vehicle Model:

KUB4X2 8.9 AUTO ABS TURBO 2WD

Primary Colour:

Multicolor

Manufacturing Year:

2008

Engine No.:

6376538

Chassis No.:

YS2K4X20001861340

Maximum Power Output:

-

Open Market Value:

\$309,418.00

Original Registration Date:

18 Aug 2008

First Registration Date:

18 Aug 2008

Transfer Count:

0

Actual ARF Paid:

\$15,471.00

Intended PARF Rebate Details

PARF Eligibility:

No

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details

COE Rebate Amount:

\$0.00

Total Rebate Amount:

\$0.00

The information contained herein is correct as at 01 Nov 2021

OK

VAN LORRY (Fru)

Buy

Vehicle No.

SBS 8308L

Front Partion

SAC	INC	Item	CON	AC	Qty
1001	991580	Fr Number Plate			
1002	991581	Fr Number Plate Base			
1004	991582	Fr Bumper			
2001	991583	Fr Bumper Upper			
2002	991584	Fr Bumper Lower			
2003	991585	Fr Bumper Side Cover			
2004	991586	Fr Bumper Side			
1006	991587	Fr Bumper Bracket			
1008	991588	Fr Bumper Reinforcement			
2005	991589	Fr Bumper Signal Lamp			
1017	991590	Fr LH Bumper Fog Lamp Cover			
1018	991591	Fr RH Bumper Fog Lamp Cover			
1019	991592	Fr LH Bumper Fog Lamp			
1020	991593	Fr RH Bumper Fog Lamp			
1021	991594	Fr Grille			
1022	991595	Fr Grille Emblem			
2006	991596	Fr Grille Sticker			
1023	991597	Fr Grille Chrome Moulding			
2007	991598	Fr Panel			
2008	991599	Fr Lower Panel			
2009	991600	Fr Panel Emblem			
2010	991601	Fr Panel Sticker			
2011	991602	Fr Panel Garnish			
1024	991603	Fr Apron Panel			
2012	991604	Fr Corner Panel			
2013	991605	Fr Corner Panel Signal Lamp			
2014	991606	Fr Signal Lamp LH			
2015	991607	Fr Signal Lamp RH			
1029	991608	Fr LH Headlamp Assy			
1030	991609	Fr RH Headlamp Assy			
1031	991610	Fr LH Side Lamp			
1032	991611	Fr RH Side Lamp			
2016	991612	Fr Wiper Panel			
2017	991613	Fr Wiper Nozzle			
1120	991614	Fr Wiper Arm			
1121	991615	Fr Wiper Blade			
2018	991616	Fr Wiper Link			
2019	991617	Fr Wiper Motor			
1122	991618	Wiper Panel Garnish			
1114	991619	Fr Windscreen			
1115	991620	Fr Windscreen Rubber			
1117	991621	Fr Windscreen Sealant			
2020	991622	Fr Windscreen Outer Pillar			
2021	991623	Fr Windscreen Inner Pillar			
1118	991624	FRP Bracket			
1119	991625	FRP Unit			
2022	991626	Fr Side Mirror (Big)			
2023	991627	Fr Side Mirror (Small)			
2024	991628	Fr Side Mirror (Round)			
2025	991629	Fr Wing Mirror Stay			
1025	991630	Fr Support Panel			
1033	991631	Bonnet			
1035	991632	Bonnet Lock			
1037	991633	Bonnet Hinge			
1039	991634	Bonnet Rubber			
1042	991635	Air Con Condenser			
1043	991636	Air Con Fan Assy			
1048	991637	Air Con Liquid Pipe			
1049	991638	Air Con Receiver Drier			
1052	991639	Radiator			
1053	991640	Radiator Cowling			
1054	991641	Radiator Fan Assy			
1056	991642	Radiator Hose Top			
1058	991643	Radiator Expansion Tank			
2026	991644	Oil Cooler			
1079	991645	Power Steering Cooler Pipe			
1059	991646	Air Filter			
1060	991647	Air Cleaner Assy			
1067	991648	Battery			
1069	991649	Battery Bracket			

Cra / LH
Cra / LH

SAC	INC	Item	CON	AC	Qty
1085	991650	Engine Under Cover			
1086	991651	Engine Mounting			
2027	991652	Fr Cabin Assy			
2028	991653	Fr Cabin Mounting			
2029	991654	Fr Cabin Rear Panel			
1092	991655	Fr LH Chassis Member			
1093	991656	Fr RH Chassis Member			
1094	991657	Fr Vertical Cross Member			
1095	991658	Fr Lower Cross Member			
2030	991659	Air Con Evaporator Assy			
2031	991660	Air Con Blower			
1082	991661	Brake Master Pump Assy			
1083	991662	Brake Booster Pump Assy			
2032	991663	Brake Pedal			
2033	991664	Accelerator Pedal			
2034	991665	Clutch Pedal			
1127	991666	Steering Wheel Airbag			
1128	991667	Steering Wheel Airbag Sensor			
1131	991668	Airbag Control Unit			
1133	991669	Fr RH Seat Belt Assy			
1135	991670	Fr LH Seat Belt Assy			
1124	991671	Dashboard Assy			
1125	991672	Glove Box Cover			
1126	991673	Glove Box Compartment			
1096	991674	Fr LH Fender			
1097	991675	Fr LH Fender Inner Panel			
1100	991676	Fr LH Fender Inner Shield			
1101	991677	Fr LH Mudflap			
2035	991678	Fr LH Wheel Guard			
1102	991679	Fr LH Wheel Rim			
1104	991680	Fr LH Tyre			
1105	991681	Fr RH Fender			
1106	991682	Fr RH Fender Inner Panel			
1109	991683	Fr RH Fender Inner Shield			
1110	991684	Fr RH Mudflap			
2036	991685	Fr RH Wheel Guard			
1111	991686	Fr RH Wheel Rim			
1113	991687	Fr RH Tyre			
1253	991688	Fr LH Door			
1256	991689	Fr LH Door Protector			
1257	991690	Fr LH Door Hinge			
1258	991691	Fr LH Door Wing Mirror			
1262	991692	Fr LH Door Glass			
1263	991693	Fr LH Door Glass Regulator			
1264	991694	Fr LH Door Glass Regulator Motor			
1265	991695	Fr LH Door Rubber			
1266	991696	Fr LH Door Outer Handle			
1272	991697	Fr LH Door Inner Trim Board			
1316	991698	Fr RH Door			
1317	991699	Fr RH Door Protector			
1318	991700	Fr RH Door Hinge			
1319	991701	Fr RH Door Wing Mirror			
1323	991702	Fr RH Door Glass			
1324	991703	Fr RH Door Glass Regulator			
1325	991704	Fr RH Door Glass Regulator Motor			
1326	991705	Fr RH Door Rubber			
1327	991706	Fr RH Door Outer Handle			
1333	991707	Fr RH Door Inner Trim Board			
2037	991708	Fr Door Frt Pillar			
2038	991709	Fr Door Rear Pillar			
2039	991710	Fr Wheel Arch Panel			
2040	991711	Fr Wheel Arch Panel Garnish			
2041	991712	Fr Step Panel			
2042	991713	Fr Step Panel Top Garnish			
2043	991714	Fr Step Panel Inner Garnish			
1073	991715	Wiper Washer Tank			
1136	991716	Sucker			

No of Items

Amount

Thruvan