

Site: (P.O.) Thuvan

CS/ASG 21010873/Vuf3

ASSIGNMENT

From:

Date:

Estimated Cost:

QD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 1 day days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date/Time

Action / Instruction

GIA in views

Date/Time File Pass to?

☐

Provl. Report

U

☐

Final Report

Date/Time File Return to?

U

Request Form:

Letter Sign / M/S: 1

Days Of Repair:

Resurvey No. of Trlp:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

W/S&I and (\$

Survey Fee:

Transportation:

S + RS. SI

Finals

Others

Total

Veh No:

SBS 8308 L

Vr Rogn:

18/8, 2008

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Scania KUB4X2

c.c 8867

Colour

Multi Colour

A/C: Insured / Std / Nil / NA

Sp. Reading

1218149.9

T/Radio: Insured / Std / Nil / NA

Eng/No:

C/No:

YS2h4X2000 1861340

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt / or

Brake: In order / Jammed / Leaked / Burnt / or

Modi: Nil / S/Rim / STD A/Rim / or

Tyre Size:

F: 275/70 R22.5

R: 275/70 R22.5

BS/OUN/EXNOVA/GY/FS/LIZA/MIC/OHTSU/PIR/SUMI/

TOYO/YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

21/10/21

D.O.A.

22/10/21

141630

Survey held at

bedon bus depot

Des. of Damages

Fr

Rear / O/S / N/S / U/C / Roof/tp or

The U/C / Chassis frame / Body Structure affected due to collision.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company
Owner ID: 653M

Vehicle Details

Vehicle No.: SB58308L
Vehicle to be Exported: Yes
Intended Deregistration Date: 01 Nov 2021
Vehicle Make: SCANIA
Vehicle Model: KUB4X2 8.9 AUTO ABS TURBO 2WD
Primary Colour: Multicolor
Manufacturing Year: 2008
Engine No.: 6376538
Chassis No.: YS2K4X20001861340

Maximum Power Output: -
Open Market Value: \$309,418.00
Original Registration Date: 18 Aug 2008
First Registration Date: 18 Aug 2008
Transfer Count: 0
Actual ARF Paid: \$15,471.00

Intended PARF Rebate Details

PARF Eligibility: No
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Rebate Amount: \$0.00
Total Rebate Amount: \$0.00

The information contained herein is correct as at 01 Nov 2021

OK

Vehicle No. 8308L

VAN LORRY (Fru)

BayS

Vehicle No.

SBS 8308L

Front Parton

SAC	INC	Item	CON	AC	Qty
1001	991586	Fr Number Plate			
1002	991587	Fr Number Plate Base			
1004	991588	Fr Bumper			
2001	991589	Fr Bumper Upper			
2002	991590	Fr Bumper Lower			
2003	991591	Fr Bumper Side Cover			
2004	991592	Fr Bumper Side			
1006	991593	Fr Bumper Bracket			
1008	991594	Fr Bumper Reinforcement			
2005	991595	Fr Bumper Signal Lamp			
1017	991596	Fr LH Bumper Fog Lamp Cover			
1018	991597	Fr RH Bumper Fog Lamp Cover			
1019	991598	Fr LH Bumper Fog Lamp			
1020	991599	Fr RH Bumper Fog Lamp			
1021	991600	Fr Grille			
1022	991601	Fr Grille Emblem			
2006	991602	Fr Grille Sticker			
1023	991603	Fr Grille Chrome Moulding			
2007	991604	Fr Panel			
2008	991605	Fr Lower Panel			
2009	991606	Fr Panel Emblem			
2010	991607	Fr Panel Sticker			
2011	991608	Fr Panel Garnish			
1024	991609	Fr Apron Panel			
2012	991610	Fr Corner Panel			
2013	991611	Fr Corner Panel Signal Lamp			
2014	991612	Fr Signal Lamp LH			
2015	991613	Fr Signal Lamp RH			
1029	991614	Fr LH Headlamp Assy			
1030	991615	Fr RH Headlamp Assy			
1031	991616	Fr LH Side Lamp			
1032	991617	Fr RH Side Lamp			
2016	991618	Fr Wiper Panel			
2017	991619	Fr Wiper Nozzle			
1120	991620	Fr Wiper Arm			
1121	991621	Fr Wiper Blade			
2018	991622	Fr Wiper Link			
2019	991623	Fr Wiper Motor			
1122	991624	Wiper Panel Garnish			
1114	991625	Fr Windscreen			
1115	991626	Fr Windscreen Rubber			
1117	991627	Fr Windscreen Sealant			
2020	991628	Fr Windscreen Outer Pillar			
2021	991629	Fr Windscreen Inner Pillar			
1118	991630	FRP Bracket			
1119	991631	FRP Unit			
2022	991632	Fr Side Mirror (Big)			
2023	991633	Fr Side Mirror (Small)			
2024	991634	Fr Side Mirror (Round)			
2025	991635	Fr Wing Mirror Stay			
1025	991636	Fr Support Panel			
1033	991637	Bonnet			
1035	991638	Bonnet Lock			
1037	991639	Bonnet Hinge			
1039	991640	Bonnet Rubber			
1042	991641	Air Con Condenser			
1043	991642	Air Con Fan Assy			
1048	991643	Air Con Liquid Pipe			
1049	991644	Air Con Receiver Drier			
1052	991645	Radiator			
1053	991646	Radiator Cowling			
1054	991647	Radiator Fan Assy			
1056	991648	Radiator Hose Top			
1058	991649	Radiator Expansion Tank			
2026	991650	Oil Cooler			
1079	991651	Power Steering Cooler Pipe			
1059	991652	Air Filter			
1060	991653	Air Cleaner Assy			
1067	991654	Battery			
1069	991655	Battery Bracket			

Cra / LH
Cra / LH

SAC	INC	Item	CON	AC	Qty
1085	991656	Engine Under Cover			
1086	991657	Engine Mounting			
2027	991658	Fr Cabin Assy			
2028	991659	Fr Cabin Mounting			
2029	991660	Fr Cabin Rear Panel			
1092	991661	Fr LH Chassis Member			
1093	991662	Fr RH Chassis Member			
1094	991663	Fr Vertical Cross Member			
1095	991664	Fr Lower Cross Member			
2030	991665	Air Con Evaporator Assy			
2031	991666	Air Con Blower			
1082	991667	Brake Master Pump Assy			
1083	991668	Brake Booster Pump Assy			
2032	991669	Brake Pedal			
2033	991670	Accelerator Pedal			
2034	991671	Clutch Pedal			
1127	991672	Steering Wheel Airbag			
1128	991673	Steering Wheel Airbag Sensor			
1131	991674	Airbag Control Unit			
1133	991675	Fr RH Seat Belt Assy			
1135	991676	Fr LH Seat Belt Assy			
1124	991677	Dashboard Assy			
1125	991678	Glove Box Cover			
1126	991679	Glove Box Compartment			
1096	991680	Fr LH Fender			
1097	991681	Fr LH Fender Inner Panel			
1100	991682	Fr LH Fender Inner Shield			
1101	991683	Fr LH Mudflap			
2035	991684	Fr LH Wheel Guard			
1102	991685	Fr LH Wheel Rim			
1104	991686	Fr LH Tyre			
1105	991687	Fr RH Fender			
1106	991688	Fr RH Fender Inner Panel			
1109	991689	Fr RH Fender Inner Shield			
1110	991690	Fr RH Mudflap			
2036	991691	Fr RH Wheel Guard			
1111	991692	Fr RH Wheel Rim			
1113	991693	Fr RH Tyre			
1253	991694	Fr LH Door			
1256	991695	Fr LH Door Protector			
1257	991696	Fr LH Door Hinge			
1258	991697	Fr LH Door Wing Mirror			
1262	991698	Fr LH Door Glass			
1263	991699	Fr LH Door Glass Regulator			
1264	991700	Fr LH Door Glass Regulator Motor			
1265	991701	Fr LH Door Rubber			
1266	991702	Fr LH Door Outer Handle			
1272	991703	Fr LH Door Inner Trim Board			
1316	991704	Fr RH Door			
1317	991705	Fr RH Door Protector			
1318	991706	Fr RH Door Hinge			
1319	991707	Fr RH Door Wing Mirror			
1323	991708	Fr RH Door Glass			
1324	991709	Fr RH Door Glass Regulator			
1325	991710	Fr RH Door Glass Regulator Motor			
1326	991711	Fr RH Door Rubber			
1327	991712	Fr RH Door Outer Handle			
1333	991713	Fr RH Door Inner Trim Board			
2037	991714	Fr Door Frt Pillar			
2038	991715	Fr Door Rear Pillar			
2039	991716	Fr Wheel Arch Panel			
2040	991717	Fr Wheel Arch Panel Garnish			
2041	991718	Fr Step Panel			
2042	991719	Fr Step Panel Top Garnish			
2043	991720	Fr Step Panel Inner Garnish			
1073	991721	Wiper Washer Tank			
1136	991722	Sucker			

No of Items

Amount

Thruvan