

Your Ref: C10010263

Date: 02<sup>nd</sup> Nov 2021

Our Ref: CS1/AGI21010879/Uqf3e2

**M/s Auto & General Insurance (S) PL**

(Budget Direct Insurance)

190 Clemenceau Avenue #03-01

Singapore Shopping Centre

Singapore 239924

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SLM 516T****INSURED VEHICLE: SKJ 8509P****ACCIDENT DATE: 13/05/2021**

We thank you for your instruction on 22/10/2021.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SLM 516T from M/s Chartered Auto Assessors.
- b) Singapore Accident Statement of Vehicles SLM 516T and SKJ 8509P.
- c) Colour damaged vehicle photographs of SLM 516T.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

## 1. Information Recorded: -

Registration Number	: SLM 516T
Make & Model	: Honda Shuttle 1.5G CVT ABS D/Airbag 2WD 5DR
Chassis Number	: GK81006718
Year of Registration	: 2017
Engine Capacity	: 1496 cc

2. We recommend that the repairs of the entire damage require about 8 (Eight) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.