

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

EQ INSURANCE COMPANY LTD

5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEX

SINGAPORE 069110

INV No. AC2107559

INV Date 03/11/2021

Reference CS/EQI21010891/Utf3n2

Code EQI

PROFESSIONAL SERVICE FEE

Vehicle No. PC 1734D

Insured Veh. GBF 7053X

Claim No. DM21HO00182/MT

Policy No.

Accident Date 28/01/2021

Inspection Date 25/10/2021

Description	Total
Survey Inspection	160.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	160.00
GST (7%)	11.20
Grand Total	171.20

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

HYN



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internation	ale Des Experts En Autor	nobile
	EQ INSURANCE C	OMPANY LTD	Ref:	CS/EQI21010891/Utf3n2
	5 MAXWELL ROAD #17-00 TOWER BL MND COMPLEXSII	OCK	Date	: 03/11/2021
			Code	e: EQI
1.		Policy Particulars :	- THIRD PARTY CLA	IM
	Insured Veh.	GBF 7053X	Veh. Inspected	PC 1734D
	Policy No.		Coverage (\$)	0.00
	Claim No.	DM21HO00182/MT	Excess (\$)	0.00
	Assign From	MELODY TEOH	Assign Date	25/10/2021
2.		Vehicle Partic	ulars & Condition	
	Make & Model	TOYOTA HIACE HIROOF (A)	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	2012
	Chassis No.	JTFST22P900014668	Colour	WHITE
	Odometer	345790 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3.	3. Conditions of Tyres			
		Size	Make	Balance
	R/H Front Tyre	195 R15	AUSTONE	6 mm
	L/H Front Tyre	195 R15	AUSTONE	6 mm
	R/H Rear Tyre	195 R15	AUSTONE	6 mm
	L/H Rear Tyre	195 R15	AUSTONE	6 mm
4.		<u>'</u>	n of Damages	
	THE VEHICLE SUS	STAINED DAMAGES AT THE FRO	ONT N/S PORTION.	
	DAMAGES SEE DE	ETAILS.		
5.		General	Information	
	Accident Date	28/01/2021	Inspection Date	25/10/2021
	Survey held at	LIU'S BROTHER AUTO ENGINE	ERING WORKSHOP	
		1 KAKI BUKIT AVENUE 6 #01-0' SINGAPORE 417883	I AUTOBAY @ KAKI BU	KIT
5a.		Re	emarks	
		N WAS CONDUCTED ON A"WITH		
5b.	B)IN ACCORDANC	E TO YOUR INSTRUCTIONS, WI	= HAVE NOT AUTHORI Days of Repair	SED KEPAIKS.
JD.	ESTIMATED NORM	MAL PERIOD FOR REPAIR:	•	rking Days
	LOTINATED NOR	WALLERIOD FOR RELAIR.		ining Days



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PC 1734D

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	DENTED	796.80	785.10
1	SET FRONT BUMPER CLIPS	NECESSARY	60.00	50.00
1	FRONT BUMPER GRILLE	NOT NECESSARY	182.50	-
	LESS 25% DISCOUNT		-	-208.78
			1,039.30	626.32
	<u>LABOUR</u>			
	LABOR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN & REPLACING PARTS ETCS.		200.00	150.00
			200.00	150.00
	GRAND TOTAL		1,239.30	776.32

RECOMMENDED COST OF LUMP SUM REPAIRS		650.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/EQI21010891/Utf3n2

CHUA KANG SENG

Licensed Appraiser

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate 5. Intribution provided must be as truthful and accurate as possible. Any white misteries entailed of withouting of material facts may allow insurance companies to reputing policy liability.
 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
 5. Any false reporting may be referred to the Police for investigation.
 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving

- and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 28/01/2021 19:59 (SGT) Date of Accident 28/01/2021 14:50 (SGT) Exact Location of Accident 145 Silat Ave, Singapore Additional Location Information Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number PC1734D

INSURED/POLICYHOLDER

Is company? Name Of Registered Owner GOLDBELL LEASING PTE LTD Company Reg No 199001196N Email Address isaacngcl@gbl.com.sg Mobile Phone No (Phone) +65-97554743 Alternative Phone No (Office) +65-64942897

VEHICLE PARTICULARS

Manufacturer Toyota Model Hiace Variant Exact purpose for which vehicle was being used at time of

accident

Are you claiming under your own insurance policy for repair to your vehicle? Vehicle Category Employment

No - Claiming third party Commercial vehicle

INSURANCE COMPANY

Name of Insurance Company First Capital Type of Coverage **ThirdParty** Fleet Policy Yes Policy Number D-20095634 Cover Note Number

DRIVER

Name of Driver LIOW KWOK TUNG NRIC No S7016517A Date Of Birth 19/05/1970 Occupation Outdoor

Date Of Driving Pass 30/11/1992 Driving experience 28 YEARS AND 2 MONTHS Gender Mobile Number (Phone) +65-97554743 Alt. Phone Number Email Address ktliow@hotmail.com Address BLK 306C PUNGGOL PLACE #14-11 Address complement Postcode 823306 Is the driver the policyholder? Nο If No, Relationship of the Driver with the Insured Hirer Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Collided into Parked Vehicle Weather Conditions Raining Road Surface Wet OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other material or property damaged? Yes Number of Passengers (Including Driver) 1 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No DETAILS OF POLICE ACTION Was the accident reported to the police? Nο Was notice of intended Prosecution given? No If yes, against whom? CIRCUMSTANCES OF ACCIDENT ON 28/1/2021, AT ABOUT 1450HRS, I PARKED MY VEHICLE PC1734D AT BLK 145 SILAT AVE OPEN SPACE CARPARK. WHILE MY VEHICLE ENGINE WAS OFF AND I WAS INSIDE MY VEHICLE, VEHICLE B - GBF7053X WAS REVERSING AND HIT ONTO MY FRONT BUMPER OF MY VEHICLE. EXCHANGED CONTACT NUMBERS. NOBODY WAS INJURED. ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? No Was there any audio recorded? No **DETAILS OF OTHER VEHICLE PROPERTY 1**

 Vehicle Registration Number
 GBF7053X

 Vehicle Manufacturer

 Vehicle Model

 Vehicle Variant

 Vehicle Colour

 Vehicle Category
 Commercial vehicle

 Name of Driver
 MR WONG

 Contact Number
 (Phone) +65-91097796

 Address

 Address complement



Postcode	_
nsurance Company Name	_
Nature Of Damage	_
Details of property damaged in accident	_
No. Of Passenger (Including Driver)	1

SKETCH PLAN

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Formmust be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time コターレンのコートします Witnessed by Reporting Centre Personnel Whosen

Sketch Plan

	nstances of the Accident
	A CONTRACT OF UM
	Oh 24/1/2021, at about 1450hm, I was
	my rehids pe 17340 alot BLR 145 SILAT AVE
sued	my rehids pe 1734D alof Br 143
	in labele in a laid empire was off
ou sp	ace coopered. While my vehicle engine was off
	5 - St. M. Welle, Vehicle B-GBF 7053
nd I	was intide my vehicle, vehicle B-GBF 7053
PRINCES VALUE AND A	and hid outo my should surregar or
al reve	. Exchenaged contact number. Notody wer
Mile	. Exchenaged contact number. 100,000
ijwed	
900	
- P	
10 10 10 10 A	

Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (* driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. PC 1734D

INSPECTION















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R











51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. PC 1734D

RE-INSPECTION









