

ASS. REC. BY: Marcus

REF:


CS/EP121010891/14+3

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: **PC 1734D**
 at Workshop m/s **14530**
 of _____
 Insured: **GBF7053X**
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: **£15k.**
 IDAC Accident Rpt: Consistent?: Yes or No
 GIA / PR Seen: Consistent?: Yes or No
 Est. Repairs: **2** days Res.: Yes or No
 Lum Sum: **15** % 3 Val.: Yes or No
196N
 CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: **LTA 5874**
 Vehicle: IN / OUT

Veh No: **PC 1734D** Yr Regn: **30/10/12**
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or **CA / Hroof**
 Make: **Toyota hiace** c.c. **2982**
 Colour: **white** A/C: Insured / Std / NI / NA
 Sp. Reading: **345790** T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: **JTFST22P900014668**
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: **border** / Jammed / Leaked / Burnt or
 Brake: **border** / Jammed / Leaked / Burnt or
 Modi: **N** / S/Rim / STD A/Rim or
 Tyre Size: **F: 195 R15**
R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or **Austone.**

Front Rear
 R/Bal. **6** mm R/Bal. **6** mm
 L/Bal. **6** mm L/Bal. **6** mm
 D.O.A. **28/1/14** D.O.I. **25/10/14**
 Survey held at _____

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or
fnt n/s.
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

We unt. 1 28-10-2012
Note new bumper replacement

28/10/14 4/5 @ 650 confirmed with Susan
red: 599.30;47%

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: **2**

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$)

) __ \$ + RS __ \$

☐ : Interview (\$)

) Photos

☐ : Tech. Invs (\$)

) Others

☐ : Weekend (\$)

)

Report Format :

Lump Sum / I.B.I.: (\$)

TOTAL

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883
 ROB No: 53291793J . Tel: 6741-1730 / 731 . Email: liusbro@gmail.com

Invoice/Ref No PC1734D210128

Estimate

Customer

Name: EQ Insurance Company Limited

Address: Motor Claims Department

5 Maxwell Road #17-00

Tower Block MND Complex Singapore 069110

Date: 22-10-21

Vehicle No: PC1734D

Model/Make: Toyota Hiace

Hi-Roof Auto 14 Seater

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Front Bumper <i>WD 785.10</i>	\$ 796.80	
2	Bumper Clips 1 set <i>new</i>	\$ 60.00	
3	Bumper Grille <i>new</i>	\$ 182.50	
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 200.00	

Total Parts & Labour of estimate for damaged vehicle

\$ 1,239.30

Total amount in Lump Sum Basis for repaired vehicle

SDLS:



M/s Liu's Bro Auto Engrg Wks

*not Authorized
 names here
 25/10/21
 1/5 @ 650
 2 days.*

*2-835-10
 257
 2-626.32
 2-150
 776.32
 152
 659.*

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis.
- No illegal modification(s) is allowed
- Supplementary Item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:

Company

Owner ID:

196N

Vehicle Details

Vehicle No.:

PC1734D

Vehicle to be Exported:

No

Intended Deregistration Date:

23 Oct 2021

Vehicle Make:

TOYOTA

Vehicle Model:

TOYOTA HIACE HIROOF AUTO 14 SEATER

Primary Colour:

White

Manufacturing Year:

2012

Engine No.:

1KD2215255

Chassis No.:

JTFST22P900014668

Maximum Power Output:

-

Open Market Value:

\$37,122.00

Original Registration Date:

30 Oct 2012

First Registration Date:

30 Oct 2012

Transfer Count:

1

Actual ARF Paid:

\$1,857.00

Intended PARF Rebate Details

PARF Eligibility:

No

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details

COE Expiry Date:

29 Oct 2022

COE Category:

C - Goods Vehicle & Bus

COE Period(Years):

10

QP Paid:

\$57,809.00

COE Rebate Amount:

\$5,874.00

Total Rebate Amount:**\$5,874.00**

The information contained herein is correct as at 23 Oct 2021

OK

INSURER ENQUIRY

Find
insurer

Vehicle reg. no.

GBF7053X

Date of Accident

26/01/2021 

Reset

% RESULT & RECEIPT

TP Insurer Enquiry

Insurance EQ Insurance Company Ltd

Period of Insurance 20/02/2020 - 19/02/2021

Requested By Susan Low (Liu's Brother Auto...)

Requested Date 22/10/2021 15:54

Payment details

Request Amount: **S\$1.87**GST Amount: **S\$0.13**Total Amount Due (GST Inclusive): **S\$2**

General Insurance Association

Records Management Centre

GST Registration No: **M400017735**