

Your Ref: CMTD2001287/GPL

Date: 18<sup>th</sup> Nov 2021

Our Ref: CS1/LAW21010931/Gqf3e2

**M/s Sompo Insurance Singapore PL**

C/ O: Chey LLC

20 Havelock Road

#02-47 Central Square

Singapore 059765

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SKD 8647E****INSURED VEHICLE: YP 8346U****ACCIDENT DATE: 14/03/2020**

We thank you for your instruction on 25/10/2021.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SKD 8647E from M/s Impact Analysis Consultant.
- b) Survey report by Priority Services with colour photographs.
- c) Singapore Accident Statement and Police Report of Vehicles SKD 8647E and YP 8346U.
- d) Colour damaged vehicle photographs of SKD 8647E.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

## 1. Information Recorded: -

Registration Number	: SKD 8647E
Make & Model	: Volkswagen Passat CC (A)
Chassis Number	: WVWZZZ3CZCE540247
Year of Registration	: 2012
Engine Capacity	: 1798 cc

2. We recommend that the repairs of the entire damage require about 5 (Five) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.