

(08/11/13) wef.
ASS. REC. BY: *Marcel*

REF: *CCG/CT121010939/Ueq3*

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / P / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *SNB5672B*
at Workshop m/s: *soon Sen*
of: *GRK 93921*
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: *\$68k.*
IDAC Accident Rpt: Consistent?: Yes or No
GIA / PR Seen: Consistent?: Yes or No
Est. Repairs: *3* days Res.: Yes or No
Lump Sum: *20* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: *LTA \$31382*

Date / Time Action / Instruction

1/11/14
have video.
4/5 @ 2500 confirmed with Vincent.

Veh No: *SNB5672B* Yr Regn: *05/04/19*
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or *CA /*
Make: *Toyota vior* C.C. *1496*
Colour: *grey* A/C: Insured / Std / NI / NA
Sp.Reading: *10382* T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: *MR2B23F 3801171653*
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / SRM / STD A/Rim or
Tyre Size: F: *195/50 R 15*
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or *Turanza*
Front Rear
R/Bal. *S* mm R/Bal. *S* mm
L/Bal. *S* mm L/Bal. *S* mm
D.O.A. *22/10/14* D.O.I. *26/10/14*
Survey held at _____
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
6/5 diff.
The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Report Format :

Lump Sum / I.B.I.: (\$)

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

) S + RS SI

) Photos

) Others

TOTAL

SOON SAN MOTOR TRADING

Blk.3006,UBI ROAD 1,#01-390,SINGAPORE 408700,TEL:68414445 & FAX:67473546

To: Motor Claims Dept

LUK ASHER

Email: soonсанmotor@gmail.com

CHINA TAIPING INSURANCE (S) PTE LTD. *hence notify*

3, Anson Rd #16-00

Springleaf Tower

S,pore 079909

Accident date:22/10/2021

Date:25/10/2021

the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

*not Admit
 run
 1/5 \$2500/
 3 days.
 26/10/21
 telephic After 14...
 90996608*

Estimate cost to repair vel: SNB 5672B (Toyota Vios) claims under vel: GBK 9399J.

1pce right front door	\$ 849.30	<i>50/sep</i>
2pcs right front door hinges @\$81.20	162.40	<i>lower half 1/2 c</i>
1pce right front door weather strip	157.70	<i>new</i>
1pce right front fender	602.40	<i>Bulldozer</i>
1pce right front fender inner shield	275.50	<i>2.5</i>
10pcs right front fender inner shield clips \$5	50.00	<i>new</i>
<i>1pc</i> sport rim <i>0/5</i>	1,000.00	<i>Cur 500 s/w</i>
1set front shock absorber	463.80	<i>17X</i>
1pce right lower arm	1,001.40	<i>17X</i>
1pce right knuckle arm	544.70	<i>17X</i>
1pce right knuckle arm bearing	180.50	<i>17X</i>
	\$ 5,287.70	
Less 20% <i>257</i>	1,057.54	
	\$ 4,230.16	
To rustproof	200.00	<i>60</i>
To computer wheel alignment	140.00	<i>80</i>
To dismantle/renew door	150.00	<i>60</i>
To dismantle/renew undercarriage front	200.00	<i>17X</i>
To dismantle /renew accident portion	1,200.00	<i>400</i>
To spray paint	1,000.00	<i>600</i>
Total:	\$ 7,120.16	

*2-2016-1
 257
 P-1512-07
 S.W. 500
 L. 1200
 32207
 2009*