FAQ English (SG) ▼ Elaine Kuan ▼

Service Requests

Messages

Claim S1M03KQC

Reference CS3/ASM21010944/Gqy3e2

Ø.

Loss Date 24 October 2021

Vendor Name LKK AUTO CONSULTANTS

PTE LTD (TP)


Type of Loss Third Party Vehicle Damage

Report Date 26 Oct 2021 9:27:01 AM

Request Date 26 October 2021

Due Date

Services Pre-Repair Survey



Vehicle Information

Incident FBS8346B

Vehicle

Registration #

Make TPVD YAMAHA

Model X-MAX

Service Address

, , ,

Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD 383 SIN MING DRIVE, 575717, Singapore 65551188

