



Claim	S1M03KQC
Reference	CS3/ASM21010944/Gqy3e2 
Loss Date	24 October 2021
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Report Date	26 Oct 2021 9:27:01 AM
Request Date	26 October 2021
Due Date	
Services	Pre-Repair Survey

Actions

Next Step

Wait for: Approve
invoice

Add Invoice

Vehicle Information

Incident	FBS8346B
Vehicle Registration #	
Make	TPVD YAMAHA
Model	X-MAX

Service Address

’ ’ ’

Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

Additional Instructions

- Messages3
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes

Document Type

Document SubType

+ Upload Documents

Already Attached

NAME		DATE UPLOADED		
NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 ASM-LKKInvoice-AC2107509.pdf.pdf	Email Sent	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	1 November 2021
 LKKPreRepairInspection.pdf.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	1 November 2021

FAQ

English (SG) ▾

Elaine Kuan ▾

Home

Service Requests

...

lence

Photos

<