



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



AUTOMOBILE INSPECTION REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC21010962/R1qcn2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 09-11-2021
189556

Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBK 8233K	Veh. Inspected	SHA 7747H
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1149902-001	Excess (\$)	0.00
Assign From		Assign Date	25/10/2021

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI IONIQ 1.6 DCT	c.c	1580
Engine No.	HIDDEN	Year of Reg.	2021
Chassis No.	KMHC851CVLU195021	Colour	BLUE
Odometer	5372	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	MICHELIN	6 mm
L/H Front Tyre	195/65 R15	MICHELIN	6 mm
R/H Rear Tyre	195/65 R15	MICHELIN	6 mm
L/H Rear Tyre	195/65 R15	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	22/10/2021	Inspection Date	25/10/2021
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------