

Our Job Ref No : 305491937

Date : 27/10/21

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

**FINALIZATION FORM**

To : LKK

Fax :

Attn : Mr RASUL

Vehicle Reg No. : SHA9535P CCPL

23/10/2021

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- SLD2559D

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

**Total for Part-By-Part Repair Cost** \$0.00

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: 20%

**Final Lumpsum Repair cost** \$3,800.00

3. Estimated normal period for repairs: 4 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : MS. LOKE YY

Tel : 62148355

Fax : 65468156

Signature : 

Name : RASUL

Date : 29/10/21

**For Official Use Only**

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks: