

MYCABS PTE LID

REPAIR ESTIMATE*

VEHICLE NO SHC72808
 MAKE REG 17.08.2017
 MODEL TOYOTA PRIUS G4

DATE 22/10/2021
 CHIANG/CHINA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER <i>de</i>			\$458.60
1	REAR BUMPER LOWER COVER <i>de</i>			\$552.60
1	REAR BUMPER REINFORCEMENT ?			\$318.80
1	REAR TRUNK LID PRIUS <i>ne</i>			\$52.40
1	REAR TRUNK LID HYBRID <i>ne</i>			\$52.90
1	REAR BUMPER TOW COVER <i>sc2</i>			\$82.70
10	REAR BUMPER CLIP <i>ne</i>			\$22.00
	SUB TOTAL			\$1,540.00
	25.00%			\$385.00
	DISCOUNTED TOTAL			\$1,155.00
1	BUMPER MAT <i>X</i>			\$50.00
1	REAR TRUNK CONFORT APP <i>ne</i>			\$40.00
1	REAR TRUNK COMFORTDELGRO & TEL NO. <i>ne</i>			\$60.00
1	BUMPER ADVERTISEMENT <i>ne</i>			\$50.00
1	BUMPER REVERSE SENSOR ?			\$135.70
				\$335.70
	Labour Charge			
	Panel Beating			350 \$570.00
	Spray Painting Charge			500 \$600.00
	Check Wiring & Lighting			X \$60.00
	Remove/Refix Reverse Sensor			40 \$60.00
	TOTAL LABOUR			\$1,290.00
	ESTIMATE TOTAL			\$2,780.70

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

RASUL
Hp 90010068
3 days
4/8
25/10/21 @1535
Resurvey after repair

Workshops

Date/Time: 23.10.2021 10:24

Page : 1

ARC Repair TP(CFSO)1

JOB CARD Sales Order: 4132712


JC NO305491880

CITYCAB PTE LTD 7010070 383 SIN MING DRIVE Singapore SINGAPORE 575717 65551188 (O) ACCOUNT CARD NO.	REGN NO.: SHC7280B	MILEAGE
	MAKE: TOYOTA	FUEL E.....1/2.....F
	MODEL: PRIUS HYBRID(G4)23.	DATE/TIME IN 10.2021 08:10
	YR OF MANU. 17.08.2017	TARGET DATE
	CHASSIS CODE JTDKB3FU003562722	COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 22.10.2021
NATURE: 3P 22.10.2021

S/NO LABOR CODE DESCRIPTION



CHECKED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.: **SHC7280B** **CHIANG**

Vehicle No.: **SHC7280B**

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard