

ASS. REG. BY:

REF:

072/

Kenora

## ASSIGNMENT

From:

Date:

Estimated Cost:

CO/PAWS/UP RES/CO RES/EVA/INV/MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Est. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / FR Seen:

Consistent?: Yes or No

Est. Repairs:

1 1/2 days

Res.: Yes or No

Lum Sum:

1-B.1%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHD 9953A

Yr Regn:

01, 21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Pwr

C.C.

179P

Colour

M.P. white / Pwr

AC:

Insured / Std / NI / NA

Sp. Reading

51529

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDK B3FU 70 3093449

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD / Rlm or

Tyre Size:

F:

Pwr

195/65R15

R:

Pwr

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

7

mm

L/Bal.

9

mm

L/Bal.

7

mm

D.O.A.

22/10/21

D.O.I.

25/10/2021

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS, SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format:

Lump Sum / I.B.I. (\$