

## **SMRT Accident Vehicle Repair Estimates**

Section A - Accident Details					
Registration Number	SMB234C				
Case Reference Number	BUS/10/21/5013				
Registration Date	1/30/2012				
Company Type	SMRT Buses Ltd				
Make	MAN				
Model	A22				
Name of Driver	Ananthanvemal				
Type of Accident	Side Swipe				
Accident Date and Time	10/9/2021 12:04 PM				
Accident Reported Date and Time	10/9/2021 2:45 PM				
Is Surveyor Required?	No				
Survey by					
Vehicle is Towed Back?	No				
Towed Back Date and Time					
Replacement Vehicle issued?	No				
Job Card Number					
Special Instruction to ARC,if any	SMB234C-RIGHT REAR PORTION SKB936J (TP) INSURED WITH NTUC				
Prepared Date and Time	10/22/2021 10:45 AM				
Chassis Number	WMAA22ZZ9C7001240				
Mileage					
Work Shop					
Repair Completion Date and Time					

Section B - Summary of Repair Estimates						
Summary of Repair Estimates						
	Quotation from ARC	Adjusted by Surveyor, if applicable				
Total Labour Cost	\$530.00	\$0.00 265				
Total Spray Cost	\$616.00	\$0.00 354				
Total Spare Part Cost	\$0.00	\$0.00				
Total Other Cost	\$0.00	\$0.00				
TOTAL COST	\$1,146.00	\$0.00				
Lump Sum Total	\$0.00	\$0.00				
Number of Repair Days	2.0	1 day				
Prepared / Adjusted By	Jeong Choon Hwee	Taufikh				
ARC / Surveyor Sign Off Date						
Signature	8	taufikh				
Remarks						

	Section C - Quotation and Accident Invoice Details					
Quotation Number		Invoice Number				
Quotation Date		Invoice Date				
Invoice Amount		Prepared Date				

## SMRT Automotive Services Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

Date Generated: 22/10/2021 User ID : JeongCH

## LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Co. pany

Acknowledged by Repairer Signature: Date:

Taufikh 97495749 WP 23/20/21 @3PM Resurvey after repair 1 day taufikh@lkkkauto.com



## **SMRT Accident Vehicle Repair Estimates**

SMRT Automotive Services Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

Date Generated : 22/10/2021
User ID : JeongCH

Section D - Details of Repair Estimates									
Part 1 - Labou	ır Works								
Job Scope			Quotation from AR				Adjusted by Surveyor, if applicable		
TO REPAIR REAR RHS PORTION			\$530.00				265		
Total Labour			\$530.00	\$530.00					
Part 2 - Spray	Painting & Pa	nnel Beating Rela	ted Works						
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS			\$616.00				354		
Total Spray Painting & Panel Beating			\$616.00						
Part 3 - Other	Costs - Accid	ent and Accident	Repair Related Exper	nse					
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
Total Other Costs									
Part 4 - Spare	Parts / Materi	al Usage							
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
Total									
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									