

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	AXA INSURANCE I	PTE LTD		Ref:	CC4/ASM21010997/Tga3q2	
	8 SHENTON WAY AXA TOWERSING			Date:	20/07/2022	
	ATTN:YVONNE			Code:	ASM	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SH 6325G	Veh. Inspected	l	SLD 978R	
	Policy No.	P2419138	Coverage (\$)		0.00	
	Claim No.	S1M03KS7	Excess (\$)		0.00	
	Assign From		Assign Date		26/10/2021	
2. Vehicle Particulars & Condition						
	Make & Model	MAZDA 3	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2016	
	Chassis No.	JM6BM42A8G0327798	Colour		WHITE	
	Odometer	78828 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	215/60 R16	YOKOHAMA		6 mm	
	L/H Front Tyre	215/60 R16	YOKOHAMA		6 mm	
	R/H Rear Tyre	215/60 R16	YOKOHAMA		6 mm	
	L/H Rear Tyre	215/60 R16	YOKOHAMA		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	25/10/2021	Inspection Dat	е	27/10/2021	
	Survey held at	RICO 60 AUTO SERVICES PTE	LTD			
		8 KAKI BUKIT AVENUE 4 #02-24 PREMIER @ KAKI BUKIT SINGAPORE 415875				
5a.	a. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORM	MAL PERIOD FOR REPAIR:		5 Worki	ng Days	