



Certification for Bus Repairs

CBR REF NO. : BB20214524

Depot :

BB

Report No.: W45662021

BUS VEHICLE NO. : SBS8309J

Driver's Co no. & Name :

78456 Tang Wei Chier

Accident Date :

22/10/2021

Date in : 22/10/2021

Date Out : 29/10/2021

Yr Of Reg	Make / Model	Chassis No.
2008	Scania KUB4X2, SD, AC, 2 Axle	YS2K4X20001861379

Stock Code	Description	Quantity	Total Material cost(S\$)
		0	\$0.00
30117414	GLASS.SIDE.1595X1228MM.O/N/S <i>BR</i>	1	\$164.00 ✓
30117433	GLASS.SIDE.994X1228MM.O/N/S <i>BR</i>	1	\$121.00 ✓
99001048	SILKAFLEX 255 EXTRA BLACK <i>nec</i>	8	\$78.40 ✓
99002081	PAINT C6000 SCANIA PURPLE <i>nec</i>	1	\$21.12 ✓
TOTAL FOR PARTS			S\$ 384.52
S/N	Labour / Spray Painting / Contractor Cost	Amount	
1	(3) Workshop Labour for Repair and Replace Bus Damage & Parts	S\$	736.00 ✓
2	Contractor's repair charges	S\$	-
TOTAL LABOUR / SPRAY PAINTING / CONTRACTOR COST			S\$ 736.00
Repair cost of Advertisement / Livery			S\$ -
TOTAL DAMAGE			S\$ 1120.52

Certification for Bus Repairs



CBR REF NO. : BB20214524

Depot : BB Report No.: W45662021 BUS VEHICLE NO. : SBS83091
 Driver's Co no. & Name : 78456 Tang Wei Chier
 Accident Date : 22/10/2021

Date in : 22/10/2021

Date Out : 29/10/2021

Yr Of Reg	Make / Model	Chassis No.
2008	Scania KUB4X2, SD, AC, 2 Axle	YS2K4X20001861379
TOTAL DAMAGE		S\$ 1120.52
Overheads		S\$ 336.16
Towing Charges		S\$ -
Repair Period : 2 day(s)	Loss of Use	S\$ 787.34
TOTAL LOSS		S\$ 2244.02

Prepared By : Choo Wee Huat

Date : 01/11/2021

Approved By
Workshop Mgr : Sim Chee Heng

Date : 01/11/2021

	Survey Fee	refer to Group Claims
TOTAL DUE		S\$ 2244.02

Acknowledged By
Depot Safety : Samuel Chua Po-Leng

Date : 02/11/2021

* This is computer generated document and does not require signature

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Steve (LKK)
 28/10/21
 w/p
 P/P
 2 days
 Resurvey Before Spray